



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI SE
Colour	White
Year of manufacture	2013
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2024-03-31
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	30
Total items failed	13

MOT #11	2023-04-01 10:21
MOT test number	677159397152
Result	✓ Passed
Next expiry date	2024-03-31
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Nearside Rear brake back plate corroded
Advice	Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Rear brake back plate corroded

**MOT #10**

2023-03-03 11:57

MOT test number

865042237476

Result**✗ Failed**

- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Rear Service brake excessively fluctuating (1.2.1 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Inner Steering linkage ball joint has slight play Steering arm (2.1.3 (b) (i))
- Fail** Offside Front Road wheel fixing missing (5.2.1 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Fail** Offside Obligatory mirror insecure (3.3 (b) (ii))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
Rear (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Offside Rear Wheel bearing play so excessive it is likely to break up (5.1.3 (a) (ii))

**MOT #9**

2022-03-07 12:06

MOT test number

907666409890

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #8

2021-02-02 08:39

MOT test number

430670471075

Result

✓ Passed

- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #7

2020-12-21 10:22

MOT test number

903339263868

Result

✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #6

2019-12-09 13:53

MOT test number

561698210866

Result

✓ Passed

**MOT #5** 2018-12-19 16:09**MOT test number** 257831788735**Result** ✓ Passed**Minor** Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside / offside (1.1.14 (a) (ii))**MOT #4** 2018-12-19 16:09**MOT test number** 840091436430**Result** ✗ Failed**Pass with rectification** Front Position lamp not working nearside / offside (4.2.1 (a))**Minor** Nearside Side repeater with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside / offside (1.1.14 (a) (ii))**MOT #3** 2017-12-13 14:02**MOT test number** 880321157768**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Offside Front Tyre worn close to the legal limit 3mm (4.1.E.1)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened nearside / offside (3.5.1i)**MOT #2** 2016-12-13 11:47**MOT test number** 420264593575**Result** ✓ Passed



MOT #1	2015-12-15 14:15
MOT test number	906977133113
Result	✓ Passed
Advice	Offside front brake pads wearing thin (75%) worn
Advice	Nearside front brake pads worn to limit (90%) worn
Advice	N/s o/s rear brake pads wearing thin (80%) worn



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN62AXP
Plate since	2024-03-28
Current registration	EN62AXP
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-01-01
Last registration	2023-04-01
Complete history	See info



Registration #1	2013-01-01	29 mi
Registration #2	2015-12-15	40.039 mi
Registration #3	2016-12-13	50.489 mi
Registration #4	2017-12-13	58.658 mi
Registration #5	2018-12-19	66.554 mi
Registration #6	2018-12-19	66.554 mi
Registration #7	2019-12-09	75.121 mi
Registration #8	2020-05-20	85.277 mi
Registration #9	2020-05-20	85.277 mi
Registration #10	2020-05-20	85.277 mi
Registration #11	2020-05-20	85.277 mi
Registration #12	2020-05-20	85.277 mi
Registration #13	2020-05-20	85.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDZ211384