



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO ZETEC TDCI 125
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	320 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT #16	2023-08-30 16:02
MOT test number	953354346994
Result	✓ Passed
Next expiry date	2024-08-29
Advice	Under trays and engine covers fitted obscuring full view of inspection
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

MOT #15	2023-08-30 14:54
MOT test number	278936598461
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
MAJOR	Front Position lamp not working both (4.2.1 (a) (ii))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
Advice	Under trays and engine covers fitted obscuring full view of inspection

MOT #14	2022-08-23 16:21
MOT test number	257791426230
Result	✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge On the limit (5.2.3 (e))

Advice Rear heat shield insecure

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Under trays and engine covers fitted obscuring full view of inspection.

Advice Offside Rear Nail in tyre

**MOT #13**

2022-08-23 10:51

MOT test number

951903919936

Result**✗ Failed****Minor**

Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR

Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice

Rear heat shield insecure

Advice

Offside Rear Nail in tyre

Advice

Offside Rear Tyre worn close to legal limit/worn on edge On the limit (5.2.3 (e))

MAJOR

Nearside Front Position lamp missing (4.2.1 (a) (ii))

Advice

Under trays and engine covers fitted obscuring full view of inspection.

DANGEROUS

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #12

2021-08-05 15:10

MOT test number

146983323070

Result**✓ Passed****Advice**

Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice

Undertrays and engine covers fitted obscuring full view of inspection

Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11

2020-07-29 09:37

MOT test number

391523462306

Result**✓ Passed**

**MOT #10** 2020-07-28 15:12**MOT test number** 236158383852**Result** ✗ Failed**MAJOR** Offside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))**MOT #9** 2019-07-24 11:00**MOT test number** 916055567899**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #8** 2019-07-24 11:00**MOT test number** 384821634014**Result** ✗ Failed**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**MOT #7** 2018-08-06 09:46**MOT test number** 940093513330**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2017-08-11 09:44**MOT test number** 812068489112**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-07-28 14:25**MOT test number** 195015065693**Result** ✓ Passed

**MOT #4** 2016-07-28 10:52**MOT test number** 576015628194**Result** ✗ Failed**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**MOT #3** 2015-07-21 11:28**MOT test number** 856062105229**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-08-21 09:32**MOT test number** 987403334245**Result** ✓ Passed**Notice** Off side front tyre starting to wear on the inner edge**MOT #1** 2013-09-12 14:25**MOT test number** 625275853285**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-09-30
Last registration	2023-08-30
Complete history	See info



Registration #1	2010-09-30	29 mi
Registration #2	2013-09-12	52.100 mi
Registration #3	2014-08-21	61.519 mi
Registration #4	2015-07-21	70.248 mi
Registration #5	2016-07-28	76.923 mi
Registration #6	2016-07-28	76.938 mi
Registration #7	2017-08-11	81.677 mi
Registration #8	2018-08-06	87.248 mi
Registration #9	2019-07-24	92.924 mi
Registration #10	2020-06-29	95.377 mi
Registration #11	2020-06-29	95.377 mi
Registration #12	2020-06-29	95.377 mi
Registration #13	2020-06-29	95.377 mi
Registration #14	2020-06-29	95.377 mi
Registration #15	2020-06-29	95.377 mi
Registration #16	2020-06-29	95.377 mi
Registration #17	2020-06-29	95.377 mi
Registration #18	2023-08-30	95.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1958 mm
Height	1429 mm
Length	4731 mm
Wheel base	2754 mm
Max. allowed weight	2155 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	AP49377