



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 R-DESIGN LUX NAV AWD
Colour	Silver
Year of manufacture	2014
Top speed	121 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	212 BHP
Max. torque	440 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.1 mpg
CO2 emission	169 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-08-12
Pictures	6
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-08-12
Pictures	12
Listing price	View report



source: heycar.co.uk



MOT history

MOT expiry date	2024-09-27
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	14
Total items failed	1

MOT #9	2023-09-28 15:00
MOT test number	199217144716
Result	✓ Passed
Next expiry date	2024-09-27
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2023-09-27 14:48
MOT test number	142704559311
Result	✗ Failed
DANGEROUS	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin very low (1.1.13 (a) (ii))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2022-09-20 14:14
MOT test number	637114001641
Result	✓ Passed
Advice	Engine bay covers and under body trays obscuring some components

MOT #6	2021-09-23 11:52
MOT test number	224314285601
Result	✓ Passed

**MOT #5** 2020-08-06 11:21**MOT test number** 644317533767**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing age cracked (5.2.3 (d) (ii))**Advice** Engine cover and Under-tray cover fitted**MOT #4** 2019-08-13 13:49**MOT test number** 703762938351**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2018-08-30 08:31**MOT test number** 194175107300**Result** ✓ Passed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))**MOT #2** 2018-08-30 08:31**MOT test number** 469023103189**Result** ✗ Failed**Advice** Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (i))**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #1	2017-09-06 09:47
MOT test number	996994071268
Result	✓ Passed
Advice	Nearside Rear Tyre age cracked all around
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened lipped (3.5.1i)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
27 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	27 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KX64LHM
Plate since	2019-09-28
Current registration	KX64LHM
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-08
Last registration	2023-09-28
Complete history	See info



Registration #1	2014-09-08	26 mi
Registration #2	2017-09-06	27.973 mi
Registration #3	2018-08-30	32.617 mi
Registration #4	2018-08-30	32.617 mi
Registration #5	2019-08-13	38.432 mi
Registration #6	2020-08-06	42.774 mi
Registration #7	2023-09-28	42.774 mi
Registration #8	2023-09-28	42.774 mi
Registration #9	2023-09-28	42.774 mi
Registration #10	2023-09-28	42.774 mi
Registration #11	2023-09-28	42.774 mi
Registration #12	2023-09-28	42.774 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	79%
Pedestrian	48%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2120 mm
Height	1713 mm
Length	4644 mm
Wheel base	2774 mm
Kerb weight	1862 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1522159