





report date: 2024-03-29

General information

Make	TOYOTA
Model	YARIS VVT-I ICON TECH
Colour	Red
Year of manufacture	2018
Top speed	102 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	134 BHP
Max. torque	280 Nm at 4.400 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	80.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	76.3 mpg
CO2 emission	75 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 3

Date 2022-02-14

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 2

Date	2022-01-25
------	------------

Pictures 29

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-06-15

Pictures 25

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



PG18HOA report date: 2024-03-29

MOT history

MOT expiry date	2025-01-20
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #6	2024-01-18 12:41
MOT test number	327357644083
Result	✓ Passed
Next expiry date	2025-01-20
Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))	

MOT #5	2024-01-18 12:41
MOT test number	695137841754
Result	★ Failed
Pass with rectification	Nearside Track rod end ball joint has excessive play lock nut to arm loose (2.1.3
(b) (i)) Advice Offside Rear Tyr	re slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))

MOT #4	2023-01-13 13:36
MOT test number	246922371987
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on the approximately 3 mm tread. 175/65R15 (5.2.3 (e))	e inner and outer edge,
Advice Offside Rear Tyre slightly damaged/cracking or perishing 175/65R15 (5	5.2.3 (d) (ii))
Advice Nearside Front Tyre slightly damaged/cracking or perishing 175/65R15	5 (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #3 2023-01-13 13:36

MOT test number 388792410051

Result X Failed

Pass with rectification Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing 175/65R15 (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on the inner and outer edge, approximately 3 mm tread. 175/65R15 (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 175/65R15 (5.2.3 (d) (ii))

MOT #2 2022-01-21 15:43

MOT test number 890666080900

Result ✓ Passed

MOT #1 2021-03-04 14:31

MOT test number 558774438836

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	20 January 2025
Full MOT history	See MOT history

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	biotom
UMMINAI	nisiaiv
OVVIICI	IIIJCOI Y

,		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		DTA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-03-14
Last registration	2024-01-18
Complete history	See info



Registration #1	2018-03-14	9 mi
Registration #2	2021-03-04	13.507 mi
Registration #3		11.777 es
Registration #4	2022-01-21	18.992 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	83%
Children	80%
Pedestrian	63%
Safety systems	57%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3945 mm
Kerb weight	1090 kg
Max. allowed weight	1565 kg

Additional information

Fuel tank capacity	36 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11

Engine number

1NZ8489040