



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | KIA |
| Model | OPTIMA CRDI 3 ISG |
| Colour | Black |
| Year of manufacture | 2017 |
| Top speed | 121 mph |
| 0 - 60 mph | 9.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 139 BHP |
| Max. torque | 340 Nm at 1.750 rpm |
| Engine capacity | 1.685 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 55.4 mpg |
| Consumption extra urban | 76.4 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 110 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-22 |
| Pictures | 0 |
| Listing price | View report |

source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-01 |
| MOT pass rate | 83 % |
| MOT passed | 5 |
| Failed MOT tests | 1 |
| Total advice items | 15 |
| Total items failed | 0 |

MOT #6 2023-08-30 13:21

MOT test number 160416217945

Result ✓ Passed

Next expiry date 2024-09-01

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2023-08-26 13:05

MOT test number 784519449829

Result ✗ Failed**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



| | |
|---------------|------------------|
| MOT #4 | 2022-08-06 08:28 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 194140730025 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #3 | 2021-09-02 09:44 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 570842537551 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #2 | 2021-02-17 10:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 913190295346 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|---|
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
|---------------|---|

| | |
|---------------|--|
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
|---------------|--|

| | |
|---------------|--|
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
|---------------|--|

| | |
|---------------|---|
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
|---------------|---|

| | |
|---------------|------------------|
| MOT #1 | 2020-01-23 12:08 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 661273380817 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 124 |
| MOT expiry date | 1 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|----------------|
| Vehicle class | 49 |
| Band | B |
| Single payment (12 months) | £ 20,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,- |



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this KIA had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 8 |
| First mileage registration | 2017-02-17 |
| Last registration | 2023-08-30 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2017-02-17 | 17 mi |
| Registration #2 | 2020-01-23 | 16.534 mi |
| Registration #3 | 2021-02-17 | 23.831 mi |
| Registration #4 | 2022-02-29 | 25.277 mi |
| Registration #5 | 2022-02-29 | 25.277 mi |
| Registration #6 | 2022-02-29 | 25.277 mi |
| Registration #7 | 2022-02-29 | 25.277 mi |
| Registration #8 | 2023-08-30 | 25.277 mi |

More info >



Car features

The KIA factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 86% |
| Pedestrian | 67% |
| Safety systems | 71% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1860 mm |
| Height | 1465 mm |
| Length | 4855 mm |
| Wheel base | 2805 mm |
| Kerb weight | 1705 kg |
| Max. allowed weight | 2070 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 70 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|--------------|
| Number of axles | 2 |
| Engine number | D4FDGH218117 |