




report date: 2024-03-28

General information

Make	VOLVO
Model	V50 E4 D SE V50
Colour	Black
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-27
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-09
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	37
Total items failed	10

## MOT #18 2023-09-07 12:42

MOT test number 739426358377

Result ✓ Passed

Next expiry date 2024-09-09

- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Exhaust mounting defective Rear hanger (6.1.2 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view Various stone chips (3.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged Outer sidewall (5.2.3 (d) (ii))

## MOT #17 2022-09-05 11:30

MOT test number 498291973695

Result ✓ Passed

- Minor** Offside Front Windscreen damaged but not adversely affecting driver's view Chip (3.2 (a) (i))
- Advice** Road wheel slightly distorted All 4 wheels on inner edge (5.2.2 (c) (i))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Side repeater slightly discoloured (4.4.3 (a))



<b>MOT #16</b>	2021-09-10 13:42
----------------	------------------

<b>MOT test number</b>	432480355491
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #15</b>	2020-05-26 09:30
----------------	------------------

<b>MOT test number</b>	323354705723
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #14</b>	2018-10-27 08:58
----------------	------------------

<b>MOT test number</b>	566332732157
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
---------------	---

<b>Advice</b>	Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bushes (5.3.4 (a) (i))
---------------	--

<b>Advice</b>	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
---------------	---

<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
---------------	--

<b>Advice</b>	Exhaust mounting defective (6.1.2 (a))
---------------	--

<b>Advice</b>	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
---------------	--

**MOT #13**

2018-10-24 13:32

**MOT test number**

339240871010

**Result****✗ Failed**

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Advice** Exhaust mounting defective (6.1.2 (a))
- Advice** Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides rear bushes (5.3.4 (a) (i))

**MOT #12**

2017-10-25 10:09

**MOT test number**

868901618427

**Result****✓ Passed**

- Advice** Rear exhaust bracket broken but exhaust is still adequately supported
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Front Brake pad(s) wearing thin both sides (3.5.1g)
- Advice** Front Suspension arm rubber bush deteriorated but not resulting in excessive movement both sides (2.4.G.2)

**MOT #11**

2016-11-03 10:46

**MOT test number**

674139199025

**Result****✓ Passed**

**MOT #10**

2016-11-03 09:25

**MOT test number**

795915778855

**Result****✗ Failed**

- Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Nearside Front Direction indicator incorrect colour (1.4.A.2f)

**MOT #9**

2015-08-01 11:23

**MOT test number**

469603315232

**Result****✓ Passed**

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8**

2015-08-01 11:23

**MOT test number**

736233315290

**Result****✗ Failed**

- Pass with rectification** Nearside Side repeater not working (1.4.A.2c)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #7**

2014-07-23 16:59

**MOT test number**

706754404254

**Result****✓ Passed**

**MOT #6** 2013-08-06 16:42**MOT test number** 157628213270**Result** ✓ Passed**MOT #5** 2012-08-01 11:43**MOT test number** 939484512269**Result** ✓ Passed

- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2011-09-01 09:10**MOT test number** 888864441214**Result** ✓ Passed**MOT #3** 2011-08-26 18:01**MOT test number** 376518131441**Result** ✗ Failed

- Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)
- Fail** Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

**MOT #2** 2010-09-17 09:57**MOT test number** 511130060236**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt



MOT #1	2009-09-18 16:37
MOT test number	803241769264
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
9 September 2024

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	307
<b>MOT expiry date</b>	9 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-09-29
Last registration	2023-09-07
Complete history	<a href="#">See info</a>



Registration #1	2006-09-29	7 mi
Registration #2	2009-09-18	22.995 mi
Registration #3	2010-09-17	31.405 mi
Registration #4	2011-08-26	42.291 mi
Registration #5	2011-09-01	42.291 mi
Registration #6	2012-08-01	50.882 mi
Registration #7	2013-08-06	63.482 mi
Registration #8	2014-07-23	72.828 mi
Registration #9	2015-08-01	84.608 mi
Registration #10	2016-11-03	93.301 mi
Registration #11	2017-05-22	101.277 mi
Registration #12	2017-05-22	101.277 mi
Registration #13	2017-05-22	101.277 mi
Registration #14	2017-05-22	101.277 mi
Registration #15	2017-05-22	101.277 mi
Registration #16	2017-05-22	101.277 mi
Registration #17	2017-05-22	101.277 mi
Registration #18	2017-05-22	101.277 mi
Registration #19	2017-05-22	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	4014833