





report date: 2024-03-29

General information

Make	FIAT
Model	500L MULTIJET TREKKING DUALOGIC
Colour	Yellow
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	94 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 сс
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/13



VU16XMT

report date: 2024-03-29

Internet history

Entry 2

Date 2023-12-13

Pictures 8









source: g3remarketing.co.uk

Entry 1


Date 2022-01-20

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-27
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	42
Total items failed	0

MOT #8		2024-01-26 10:33
MOT test	number	623340226279
Result		✓ Passed
Next expi	ry date	2025-01-27
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Engine covers / under trays fitted	
Advice	Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Front Windscreen damaged but not adversely affecting driver's view nearside (3.2 (a) (i))

CarCheck.co.uk page 3/13



Advice

VU16XMT

report date: 2024-03-29

MOT #7 2024-01-26 09:53 563997574887 **MOT** test number Result **X** Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) Advice Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Minor Front Windscreen damaged but not adversely affecting driver's view nearside (3.2 (a) (i)) Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Tyre not fitted in accordance with side wall instructions (5.2.3 (i)) **MAJOR** Advice Engine covers / under trays fitted Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6		2023-01-28 10:22
MOT test	number	488286349741
Result		✓ Passed
Advice	Engine covers / under trays fitted	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



MOT #5 2023-01-26 12:59

MOT test number 875773311444

Result X Failed

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Engine covers / under trays fitted

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

DANGEROUS Offside Front Suspension arm pin or bush likely to become detached (5.3.4 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #4 2022-01-28 11:20

MOT test number 532197367997

Result J Passed

CarCheck.co.uk page 5/13



VU16XMT

report date: 2024-03-29

MOT test number

875632105771

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2020-03-09 14:27 **MOT** test number 162185136779 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Brake cable damaged but not to excess (1.1.15 (a)) Advice Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

MOT #1	2019-03-08 09:18
MOT test number	381499635107
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	27 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



VU16XMT

report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report \(\frac{1}{2} \)	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	m.o.o
Current registration	NK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-03-11
Last registration	2024-01-26
Complete history	See info



Registration #1	2016-03-11	14 mi
Registration #2	2019-03-08	34.619 mi
Registration #3	2020-03-09	43.672 mi
Registration #4	2021-03-11	49.683 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	78%
Pedestrian	65%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1800 mm
Height	1679 mm
Length	4270 mm
Wheel base	2612 mm
Kerb weight	1315 kg
Max. allowed weight	1855 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13