





General information

| Make | LAND ROVER | |
|---------------------|---------------------------|--|
| Model | FREELANDER SD4 HSE LUXURY | |
| Colour | Black | |
| Year of manufacture | 2013 | |
| Top speed | 118 mph | |
| 0 - 100 km/h | 11.2 seconds | |
| 0 - 60 mph | 8.7 seconds | |
| Gearbox | 6 speed automatic | |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 190 BHP |
|-------------------------|---------------------------|
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |







Internet history

Entry 1

Date

Pictures

Listing price

4

2021-09-09

View report



source: autotrader.co.uk



MOT history

| MOT expiry date | 2024-08-31 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 8 |
| Failed MOT tests | 2 |
| Total advice items | 14 |
| Total items failed | 2 |

| MOT #10 | 2023-08-25 07:30 |
|---|------------------|
| MOT test number | 770576977120 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-31 |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

MOT #9 2022-08-25 11:03 MOT test number 632880854264 Result ✓ Passed

| MOT #8 | 2021-08-18 08:47 |
|-------------------------------------|------------------|
| MOT test number | 723377939484 |
| Result | ✓ Passed |
| Advice Front axle tread getting low | |

| MOT #7 | 2020-09-01 14:25 |
|--|------------------|
| MOT test number | 364387481316 |
| Result | ✓ Passed |
| Advice Steering rack pinion misting in oil | |





| MOT #6 | 2020-09-01 14:11 |
|--|------------------|
| MOT test number | 276250034544 |
| Result | 🗙 Failed |
| FailEngine MIL inoperative or indicates a malfunction (8.2.1.2 (h))AdviceSteering rack pinion misting in oil | |

| MOT #5 | 2019-08-20 09:33 |
|-----------------|------------------|
| MOT test number | 188417111594 |
| Result | ✓ Passed |

| MOT #4 | | 2018-08-06 09:23 |
|----------|--|------------------|
| MOT test | number | 867952373738 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Emissions to clean to register | |
| Advice | Rear Inner Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) | |

| MOT #3 | 2017-08-21 09:30 |
|---------------------------------------|------------------|
| MOT test number | 756358250421 |
| Result | ✓ Passed |
| Advice Emissions to clean to register | |

| MOT #2 | | 2016-09-23 09:25 |
|----------|---|------------------|
| MOT test | number | 977661932259 |
| Result | | ✓ Passed |
| Advice | Nearside Front Outer tyre worn on edge | |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) | |





| MOT #1 | 2016-09-23 08:41 |
|--|------------------|
| MOT test number | 668268449522 |
| Result | 🗙 Failed |
| Fail Front Windscreen wiper does not clear the windscreen effectively (8.2.2) Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Nearside Front Outer tyre worn on edge | |
| | |



Tax & MOT check

| ✓ Taxed Tax due: 1 October 2024 | ✓ MOT Expires: 31 August 2024 |
|--|--|
| Tax status | Valid until 1 October |
| Days left | 156 |
| MOT expiry date | 31 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |





Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Date | |
| | MP1E |
| Category | ter . |
| Туре | |

Extra LAND ROVER salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 11.111 |
| Average private trade value | 4 10 200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ********** | | |
|---------------|-----------|---|
| ******** | | |
| ******* | | |
| *********** | | |
| ******** | | |
| | More info | > |
| | | |
| Plate changes | | |
| | | |

| Number of plates | , |
|----------------------|-------------|
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | More info > |





Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-10-22 |
| Last registration | 2023-08-25 |
| Complete history | See info |



| Registration #1 | 2013-10-22 | 6 mi |
|------------------------------------|------------|--|
| Registration #2 | 2016-09-23 | 22.556 mi |
| Registration #3 | 2016-09-23 | 22.556 mi |
| Registration #4 | 2017-08-21 | 25.389 mi |
| Registration #5 | 2018-08-06 | 36.803 mi |
| Registration #6 | 2019-08-20 | 46.166 mi |
| Registration #7 | | 11.227 mi |
| | | |
| Registration #8 | | 11.317 est |
| Registration #8 Registration #9 | | 11.577 est 11.577 est |
| - | | 01.000 est 01.000 est 01.000 est |
| Registration #9 | | 01.000 est 01.000 est 01.000 est 01.000 est |

More info \rightarrow





Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|--------------------------|
| Width | 2180 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1770 kg |
| Max. allowed weight | 2505 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 68 I |
| | 68 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |