



General information

Make	MINI
Model	COOPER S COOPER SD
Colour	Black
Year of manufacture	2014
Top speed	132 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	305 Nm at 2.700 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-06-07
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-04-26
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	20
Total items failed	10

MOT #10 2023-04-27 11:21

MOT test number 870301277940

Result ✓ Passed

Next expiry date 2024-04-26

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2023-04-27 11:21

MOT test number 275384598731

Result ✗ Failed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Pass with rectification Windscreen washer not working (3.5 (a))

**MOT #8** 2023-03-10 15:28**MOT test number** 226200424361**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Headlamp aim too low and too far to the right. (4.1.2 (a))
- Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #7 2022-02-14 17:38**MOT test number** 686866537117**Result** ✓ Passed

- Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))
- Advice** Air box loose on engine
- Advice** Items removed from driver's view prior to test hangers
- Advice** Offside Front Seat belt slightly damaged freying (7.1.2 (b) (i))
- Advice** Exhaust noisy (8.1.1 (a))

**MOT #6**

2022-02-09 17:49

MOT test number

833859806677

Result**✗ Failed****Advice** Offside Front Seat belt slightly damaged freying (7.1.2 (b) (i))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Advice** Front Exhaust has a minor leak of exhaust gases flexy (6.1.2 (a))**Fail** Shock absorbers has negligible damping effect both fronts (5.3.2 (d))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Air box loose on engine**Advice** Items removed from driver's view prior to test hangers**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Exhaust noisy (8.1.1 (a))**MOT #5**

2020-09-29 08:07

MOT test number

775837432466

Result**✓ Passed****Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4**

2019-09-26 14:34

MOT test number

212820209299

Result**✓ Passed****Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #3	2018-09-18 13:02
MOT test number	971358800656
Result	✓ Passed

MOT #2	2018-09-12 13:37
MOT test number	883264326530
Result	✗ Failed
<div><div>Fail</div>Offside Front Road wheel badly distorted (5.2.2 (c) (i))</div> <div><div>Fail</div>Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))</div>	

MOT #1	2017-07-25 10:40
MOT test number	668557420139
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✗
MOT
Expired:
26 April 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	26 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-07-26
Last registration	2023-04-27
Complete history	See info



Registration #1	2014-07-26	10 mi
Registration #2	2017-07-25	38.044 mi
Registration #3	2018-09-12	50.388 mi
Registration #4	2018-09-18	50.389 mi
Registration #5	2019-09-26	60.516 mi
Registration #6	2020-09-29	70.424 mi
Registration #7	2020-09-29	70.424 mi
Registration #8	2020-09-29	70.424 mi
Registration #9	2020-09-29	70.424 mi
Registration #10	2020-09-29	70.424 mi
Registration #11	2020-09-29	70.424 mi
Registration #12	2020-09-29	70.424 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2

Engine number	95138806
---------------	----------