



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 T SE LUX
Colour	Gold
Year of manufacture	2007
Top speed	143 mph
0 - 60 mph	7.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	30.4 mpg
CO2 emission	222 g/km
CO2 label	K



Internet history

Entry 1

Date	2021-09-14
Pictures	10
Listing price	View report









source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-10-19
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	14
Total items failed	4

MOT #19	2023-10-18 15:56
MOT test number	634541711822
Result	✓ Passed
Next expiry date	2024-10-19

MOT #18	2023-10-18 14:44
MOT test number	245682069466
Result	✗ Failed
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #17	2022-10-17 14:21
MOT test number	404779062322
Result	✓ Passed

MOT #16	2022-10-17 13:58
MOT test number	706410416706
Result	✗ Failed
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #15	2021-10-20 13:45
MOT test number	298353482530
Result	✓ Passed

**MOT #14** 2020-09-22 15:04**MOT test number** 992898015759**Result** ✓ Passed**Advice** Exhaust system corroded.**MOT #13** 2020-09-22 14:04**MOT test number** 962086419191**Result** ✗ Failed**Advice** Exhaust system corroded.**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #12** 2019-09-16 13:49**MOT test number** 366450886040**Result** ✓ Passed**MOT #11** 2018-09-04 14:59**MOT test number** 787356618025**Result** ✓ Passed**MOT #10** 2017-08-25 15:09**MOT test number** 739663937964**Result** ✓ Passed**MOT #9** 2016-09-05 12:30**MOT test number** 612628227842**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Under trays fitted obscuring some underbody components

**MOT #8** 2016-09-05 12:30**MOT test number** 887886611773**Result** ✗ Failed**Pass with rectification** Nearside Side repeater not working (1.4.A.2c)**Advice** Under trays fitted obscuring some underbody components**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2015-09-18 10:35**MOT test number** 786995448734**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-09-23 13:09**MOT test number** 427146864266**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2013-09-16 15:50**MOT test number** 185449753219**Result** ✓ Passed**MOT #4** 2012-08-30 16:17**MOT test number** 628883142291**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #3	2011-08-04 10:27
MOT test number	569526311240
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2010-09-22 12:43
MOT test number	864945960290
Result	✓ Passed

MOT #1	2010-08-20 15:58
MOT test number	132472630217
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-09-29
Last registration	2023-10-18
Complete history	See info



Registration #1	2007-09-29	17 mi
Registration #2	2010-08-20	35.844 mi
Registration #3	2010-09-22	36.891 mi
Registration #4	2011-08-04	45.085 mi
Registration #5	2012-08-30	54.771 mi
Registration #6	2013-09-16	61.706 mi
Registration #7	2014-09-23	66.307 mi
Registration #8	2015-09-18	70.295 mi
Registration #9	2016-09-05	73.390 mi
Registration #10	2016-09-05	73.390 mi
Registration #11	2017-08-25	79.035 mi
Registration #12	2018-08-20	85.277 mi
Registration #13	2019-08-20	91.519 mi
Registration #14	2020-08-20	97.761 mi
Registration #15	2021-08-20	104.003 mi
Registration #16	2022-08-20	110.245 mi
Registration #17	2023-08-20	116.487 mi
Registration #18	2024-08-20	122.729 mi
Registration #19	2025-08-20	128.971 mi
Registration #20	2026-08-20	135.213 mi
Registration #21	2027-08-20	141.455 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1731 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4202993