





General information

Make	PEUGEOT
Model	EXPERT BLUEHDI ALLURE
Colour	Silver
Year of manufacture	2019
Top speed	106 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	370 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	57.7 mpg
Consumption combined	53.3 mpg
CO2 emission	144 g/km
CO2 label	F







Internet history

Entry 2	
Date 2021-07-08	
Pictures 14	

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

14 <u>View report</u>

2021-07-08



source: autotrader.co.uk









MOT history

MOT expiry date	2024-09-29
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	16
Total items failed	2

MOT #3		2023-09-21 16:15
MOT test	number	435428390352
Result		✓ Passed
Next expi	ry date	2024-09-29
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



wv69POU report date: 2024-03-29

MOT #2		2023-09-11 13:23
MOT test	number	986276867180
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail O	ffside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail N	earside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #1	2022-09-13 12:10
MOT test number	836976518085
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm & Has	cuts in tread (5.2.3 (e))
Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge 3mm & Ha	s cuts in tread (5.2.3 (e))
Minor Offside Rear Registration plate lamp inoperative in the case of multiple (4.7.1 (b) (i))	e lamps or light sources



Tax & MOT check

✓ Taxed	√ MOT
Tax due: 1 September 2024	Expires: 29 September 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	29 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Mileage registrations	6
First mileage registration	2019-09-30
Last registration	2023-09-21
Complete history	See info



Registration #1	2019-09-30	14 mi
Registration #2		11.777 est
Registration #3		11.777 esi
Registration #4		11.777 est
Registration #5		11.777 mi
Registration #6		10.200 est



wv69POU report date: 2024-03-29

Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight	
Width	1920 mm
Height	1810 mm
Length	4959 mm
Wheel base	3275 mm
Kerb weight	1726 kg
Max. allowed weight	2750 kg
Additional information	
Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	8 page 11/11

Number of axles	2
Engine number	DY1M4008828