



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 EXECUTIVE
Colour	Grey
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 3.000 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	23.7 mpg
Consumption extra urban	37.7 mpg
Consumption combined	31.0 mpg




LABEL UNKNOWN



Internet history

Entry 6


Date	2022-02-13
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 5



Date	2022-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 4

Date	2021-12-26
Pictures	10
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 3



Date	2021-12-11
------	------------

Pictures

10

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**Entry 2**

Date


2021-06-11

Pictures

11

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**Entry 1**

Date

2021-05-28

Pictures

11

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT #23	2021-04-15 08:00
MOT test number	219090409127
Result	✓ Passed
Next expiry date	2022-04-14
Advice	All rear trailing arm bushes perished

MOT #22	2021-04-15 08:00
MOT test number	714688573142
Result	✗ Failed
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
Advice	All rear trailing arm bushes perished

MOT #21	2020-04-02 14:14
MOT test number	789498080346
Result	✓ Passed
Advice	Coolant leak

MOT #20	2020-03-30 15:36
MOT test number	417211988319
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Advice	Coolant leak

MOT #19	2019-03-06 15:05
MOT test number	282908625163
Result	✓ Passed

**MOT #18** 2019-03-06 10:06**MOT test number** 439880584223**Result** ✗ Failed**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #17** 2018-01-31 13:10**MOT test number** 385754098395**Result** ✓ Passed**MOT #16** 2016-12-21 11:07**MOT test number** 840749909091**Result** ✓ Passed**Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)**MOT #15** 2015-12-23 16:24**MOT test number** 463100890391**Result** ✓ Passed**Advice** Tailgate handle requires attention**Advice** Nearside headlight high limit and offside headlight low limit**Advice** Rear coil spring corroded both (2.4.C.1b)

**MOT #14**

2015-12-19 11:57

**MOT test number**

355770272303

**Result****✗ Failed****Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Rear coil spring corroded both (2.4.C.1b)**Advice** Nearside headlight high limit and offside headlight low limit**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Tailgate handle requires attention**MOT #13**

2014-12-20 10:41

**MOT test number**

646534154392

**Result****✓ Passed****Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Handbrake just makes minimum requirement**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #12**

2014-12-13 10:46

**MOT test number**

477267344345

**Result****✗ Failed****Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #11** 2013-12-28 12:15**MOT test number** 435552763457**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Service brake grabbing slightly (3.7.C.2)**MOT #10** 2013-08-31 11:09**MOT test number** 505253843281**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Notice** Parking brake efficiency only just met the required amount**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #9** 2013-08-31 11:09**MOT test number** 747203243224**Result** ✓ Passed**Notice** Parking brake efficiency only just met the required amount**MOT #8** 2013-02-27 13:26**MOT test number** 189258853467**Result** ✓ Passed**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** The handbrake efficiency has only just met the requirements.



MOT #7	2013-02-26 08:43
MOT test number	537647853051
Result	✗ Failed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Rear fog lamp not working (1.3.2b)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Parking brake: efficiency below requirements (3.7.C.1b)

MOT #6	2012-02-28 12:52
MOT test number	139299352032
Result	✓ Passed
Notice	Slight movement nearside front antiroll bar link.
Notice	Rear exhaust mount corroded.





MOT #5 2012-02-28 10:27

MOT test number 577769752047

Result ✗ Failed

**Notice** Slight movement nearside front antiroll bar link.

**Fail** Offside Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Front registration plate displaying a honeycomb or similar effect background (6.3.3)

**Notice** Rear exhaust mount corroded.

**Fail** Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)

**Fail** Offside Registration plate lamp not working (1.1.C.1d)

MOT #4 2010-11-25 10:04

MOT test number 483159820370

Result ✓ Passed

MOT #3 2009-12-22 11:11

MOT test number 401846159305

Result ✓ Passed

MOT #2 2009-12-17 11:47

MOT test number 232581759370

Result ✗ Failed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Fail** Parking brake: efficiency below requirements (3.7.C.1b)

**Fail** Rear brake disc excessively pitted (3.5.1h)



MOT #1	2008-12-15 11:35
MOT test number	380760358365
Result	✓ Passed
Advice	Offside Rear brake disc slightly scored (3.5.1h)
Advice	Offside Front brake disc slightly pitted (3.5.1h)
Advice	Nearside Rear brake disc slightly scored (3.5.1h)
Advice	Nearside Front brake disc slightly pitted (3.5.1h)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	29
First mileage registration	2005-11-10
Last registration	2021-04-15
Complete history	<a href="#">See info</a>



Registration #1	2005-11-10	14 mi
Registration #2	2008-12-15	47.468 mi
Registration #3	2009-12-17	37.420 mi
Registration #4	2009-12-22	57.169 mi
Registration #5	2010-11-25	65.999 mi
Registration #6	2012-02-28	82.069 mi
Registration #7	2012-02-28	82.069 mi
Registration #8	2013-02-26	94.026 mi
Registration #9	2013-02-27	94.036 mi
Registration #10	2013-08-31	100.582 mi
Registration #11	2013-12-28	102.239 mi
Registration #12	2014-12-13	121.281 mi
Registration #13	2014-12-20	121.702 mi
Registration #14	2015-12-19	141.791 mi
Registration #15	2015-12-23	141.908 mi
Registration #16	2016-05-20	151.377 mi
Registration #17	2016-05-20	151.377 mi
Registration #18	2016-05-20	151.377 mi
Registration #19	2016-05-20	151.377 mi
Registration #20	2016-05-20	151.377 mi
Registration #21	2016-05-20	151.377 mi
Registration #22	2016-05-20	151.377 mi
Registration #23	2016-05-20	151.377 mi
Registration #24	2016-05-20	151.377 mi
Registration #25	2016-05-20	151.377 mi
Registration #26	2016-05-20	151.377 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442

More info >





Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2859 mm
Kerb weight	2108 kg
Max. allowed weight	2735 kg

Additional information

Fuel tank capacity	72 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	267835
---------------	--------