





report date: 2024-03-28

General information

Make	FORD
Model	KA ZETEC
Colour	White
Year of manufacture	2017
Top speed	99 mph
0 - 100 km/h	15.3 seconds
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	51.5 kW / 70 HP / 69 BHP
Max. torque	105 Nm at 4.000 rpm
Engine capacity	1.198 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	70.6 mpg
Consumption combined	56.5 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/10



SE17OZT report date: 2024-03-28

MOT history

MOT expiry date	2025-04-02
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	5
Total items failed	12

MOT #6	2024-04-02 10:09	
MOT test number	364089366160	
Result	✓ Passed	
Next expiry date	2025-04-02	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #5	2023-04-03 15:01
MOT test number	542173316949
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #4	2022-03-28 16:15
MOT test number	404738413349
Result	√ Passed
MOT #3	2021-04-02 07:57
MOT test number	448407416897
Result	✓ Passed

CarCheck.co.uk page 2/10



MOT #2

SE170ZT

report date: 2024-03-28

2021-03-22 11:14

MOT test number 544381502354 Result × Failed Fail Nearside Rear Road wheel fixing missing (5.2.1 (a) (i)) Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c)) Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h)) Fail Fail Offside Front Road wheel fixing missing (5.2.1 (a) (i)) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front daytime running light not workingt

Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Fail Horn not working (7.7 (a) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #1 2020-06-15 05:53

MOT test number 651335446414

Result

Passed

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 3/10



SE170ZT

report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 September
Days left	126
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



SE17OZT report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



SE17OZT report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

SE170ZT

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have the check it in the premium report and see all owner registrations. Download the full report here.	nave?
NAME OF TAXABLE PARTY O	

NAME OF TAXABLE PARTY O	

 $\quad \text{More info} \quad > \quad$

Plate changes

More info >

CarCheck.co.uk page 7/10



SE170ZT report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



SE170ZT

report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2017-06-23
Last registration	2024-04-02
Complete history	See info



Registration #1	2017-06-23	7 mi
Registration #2	2021-03-22	67.109 mi
Registration #3	2021-04-02	67.112 mi
Registration #4		71.777 66
Registration #5		11.777 es
Registration #6		0.77

More info >

CarCheck.co.uk page 9/10



SE170ZT

report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1521 mm
Length	3929 mm
Wheel base	2489 mm
Kerb weight	955 kg
Max. allowed weight	1500 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 10/10