





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T30 SWB W/V 130TDI
Colour	Silver
Year of manufacture	2005
Top speed	103 mph
0 - 60 mph	16.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.460 cc
Cylinders	5
Fuel type	Diesel
Consumption city	23.9 mpg
Consumption extra urban	37.2 mpg
Consumption combined	31.0 mpg
CO2 emission	230 g/km
CO2 label	L



CarCheck.co.uk page 1/13



EK55GWE report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-23

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

Μ	OT	his	tory

MOT expiry date	2024-06-20
MOT pass rate	85 %
MOT passed	17
Failed MOT tests	3
Total advice items	11
Total items failed	16

MOT #20	2023-06-21 11:45	
MOT test number	938272018552	
Result	✓ Passed	
Next expiry date	2024-06-20	
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #19		2022-06-17 09:08
MOT test	number	525217521718
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	

MOT #18	2021-06-21 12:19
MOT test number	582552586727
Result	✓ Passed
MOT #17	2020-07-28 16:03
MOT test number	413263461068
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	Viassea

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #16 2019-07-06 13:22

MOT test number 745249532713

Result ✓ Passed

MOT #15 2018-07-11 16:37

MOT test number 141566422164

Result

Passed

MOT #14 2017-07-08 11:42

MOT test number 775049989462

Result ✓ Passed

MOT #13 2016-07-14 07:47

MOT test number 982658602769

MOT #12 2016-07-12 10:31

MOT test number 342022978465

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Pass with rectification Offside Headlamp aim too low (1.8)

Fail Nearside Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Pass with rectification Nearside Headlamp aim too low (1.8)

Pass with rectification Nearside Headlamp aim too far to the left (1.8)

MOT #11 2015-07-15 13:15

MOT test number 819226695134

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #10 2014-07-15 11:15

MOT test number 299916794170

MOT #9 2013-07-18 15:03

MOT test number 208969893422

Result

Passed

MOT #8 2013-07-18 12:40

MOT test number 516619993108

Result X Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Offside Stop lamp not working (1.2.1b)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #7 2012-07-21 11:45

MOT test number 356523702476

MOT #6 2012-06-07 15:47

MOT test number 447559852122

Result

Passed

CarCheck.co.uk page 5/13



report date: 2024-03-28

NOT "F	2011 07 11 12 56
MOT #5	2011-07-11 12:56
MOT test number	149372791180
Result	✓ Passed
MOT #4	2010-08-04 09:49
MOT test number	141916210245
Result	✓ Passed
MOT #3	2009-09-17 14:03
1101 #3	2003 03 17 1 1103
MOT test number	322010769215
MOT test number	322010769215
MOT test number Result	322010769215
MOT test number Result Pass with rectification Nearside Front Headlamp aim too high (1.8)	322010769215
Result Pass with rectification Nearside Front Headlamp aim too high (1.8) Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)	322010769215

MOT #2		2009-09-17 14:03
MOT test	number	364010969297
Result		✓ Passed
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Spare tyre defective	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	

MOT #1	2008-09-04 17:09
MOT test number	613328548228
Result	✓ Passed

CarCheck.co.uk page 6/13



EK55GWE report date: 2024-03-28

Tax & MOT check



Tax statusValid until 1 AugustDays left95MOT expiry date20 June 2024Full MOT historySee MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Example Example

Category

Type

Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



EK55GWE report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-09-28
Last registration	2023-06-21
Complete history	See info



Registration #1	2005-09-28	23 mi
Registration #2	2008-09-04	24.362 mi
Registration #3	2009-09-17	18.519 mi
Registration #4	2010-08-04	50.267 mi
Registration #5	2011-07-11	54.839 mi
Registration #6	2012-06-07	58.325 mi
Registration #7	2012-07-21	61.477 mi
Registration #8	2013-07-18	69.033 mi
Registration #9	2013-07-18	69.035 mi
Registration #10	2014-07-15	81.398 mi
Registration #11	2015-07-15	89.579 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11,177 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0295	
60482	
60501	
0566	
0567	
60569	

Dimensions & weight

Width	2242 mm
Height	1969 mm
Length	4890 mm
Max. allowed weight	3000 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	8
Engine number	AXD100562

CarCheck.co.uk page 13/13