





General information

Make	PEUGEOT
Model	5008 HDI EXCLUSIVE
Colour	Red
Year of manufacture	2010
Top speed	114 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP	0 < 10
Max. torque	270 Nm at 1.750 rpm	101 - 120
Engine capacity	1.560 cc	121 - 140
Cylinders	4	141 - 165
Fuel type	Diesel	166 - 185
Consumption city	44.1 mpg	186 - 225
Consumption extra urban	62.8 mpg	225+
Consumption combined	54.3 mpg	
CO2 emission	135 g/km	
CO2 label	E	



MOT history

MOT expiry date	2023-05-24
MOT pass rate	53 %
MOT passed	9
Failed MOT tests	8
Total advice items	28
Total items failed	23

MOT #17	2022-05-25 14:28
MOT test number	905646865577
Result	✓ Passed
Next expiry date	2023-05-24
Advice Offside Front Brake disc worn, but not excessively (1.1.14	4 (a) (i))
Advice Nearside Front Brake disc worn, but not excessively (1.1.	.14 (a) (i))
Advice Offside Front Inner Tyre worn close to legal limit/worn on	edge (5.2.3 (e))

MOT #16 2022-05-25 09:03 679681988309 **MOT test number** Result × Failed Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Position lamp not working (4.2.1 (a) (ii)) Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) Fail Front Oil leaking excessively from engine (8.4.1 (a) (i)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))



KN10	UEL
report date:	2024-03-29

MOT #15	2021-04-15 16:33
MOT test number	418344434386
Result	✓ Passed
Advice Front Lower Suspension arm pin or bush worn but not resulting in a (rear) (5.3.4 (a) (i))	excessive movement both sides
MOT #14	2021-04-08 19:03
MOT test number	102124161459
Result	🗙 Failed
Advice Front Lower Suspension arm pin or bush worn but not resulting in e (rear) (5.3.4 (a) (i))	excessive movement both sides
Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #13	2020-10-06 14:09
MOT test number	871069883015
Result	🗙 Failed
Advice Trailing arm bushes perishing	
Fail Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
FailOffside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice Both front wishbone rear bushes perishing	
Fail Oil leaking excessively from engine (8.4.1 (a) (i))	
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning	g (4.2.1 (a) (i))
Fail Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))	
Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



KN10	UEL
report date:	2024-03-29

2019-10-09 14:43

MOT #12	2019-10-11 14:00
MOT test number	617566388930
Result	✓ Passed
Advice Oil leak, but not excessive engine area (8.4.1 (a) (i))	
Advice Offside Rear Child Seat fitted not allowing full inspecti	on of adult belt

MOT #11

MOT test number	418441248419
Result	🗙 Failed
Fail Nearside Headlamp aim too far to the right (4.1.2 (a))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Oil leak, but not excessive engine area (8.4.1 (a) (i))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #10	2018-10-09 13:53
MOT test number	688716911197
Result	✓ Passed

МОТ #9		2018-10-09 13:53
MOT test number		503366127476
Result		🗙 Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))	

MOT #8		2017-07-13 08:53
MOT test	number	692462022506
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit on limit 1.6m (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #7	2016-06-16 15:40
MOT test number	304089228686
Result	✓ Passed
Advice Offside Rear wheel bearing has slight play (2.6.2)	
MOT #6	2016-06-16 11:18
MOT test number	381512669795
Result	🗙 Failed
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Offside Rear wheel bearing has slight play (2.6.2)	
Fail Emissions not tested (7.4.B.1)	

MOT #5		2015-07-03 09:42
MOT test	number	519434585196
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear wheel bearing has slight play (2.6.2)	
Notice	Child seat fitted not allowing full inspection of adult belt	



MOT #4	2015-06-26 10:30
MOT test number	509317575190
Result	🗙 Failed
Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice Child seat fitted not allowing full inspection of adult belt	
Fail Offside Headlamp not working on dipped beam (1.7.5a)	
Advice Offside Rear wheel bearing has slight play (2.6.2)	

MOT #3	2014-04-29 10:19
MOT test number	649589514171
Result	✓ Passed
Advice Offside Rear wheel bearing has slight play (2.6.2)	

MOT #2	2013-04-05 15:53
MOT test number	417155393048
Result	✓ Passed

MOT #1	2013-04-05 11:14
MOT test number	536415093077
Result	🗙 Failed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	

KN10UEL

report date: 2024-03-29





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FE D
Category	 L CENPE
Туре	K K
Damage 2	AMPL
Date	
Category	 AMPL
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



KN10UEL report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-04-07
Last registration	2022-05-25
Complete history	See info



Registration #1	2010-04-07	17 mi
Registration #2	2013-04-05	32.197 mi
Registration #3	2013-04-05	32.197 mi
Registration #4	2014-04-29	41.505 mi
Registration #5	2015-06-26	53.304 mi
Registration #6	2015-07-03	53.304 mi
Registration #7	2016-06-16	62.687 mi
Registration #8	2016-06-16	62.693 mi
Registration #9	2017-07-13	72.817 mi
Registration #10		11.777 est
Registration #11		11.707 est
Registration #12		11.777 est
Registration #13		11.707 est
Registration #14		11.777 est
Registration #15		11.777 est
Registration #16		11.777 est
Registration #17		11.777 mi
Registration #18		10.200 est





Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	86%
Children	81%
Pedestrian	31%
Safety systems	97%
Overall rating	75%
Video	see crash video



Dimensions & weight	
Width	1837 mm
Height	1640 mm
Length	4365 mm
Wheel base	2613 mm
Kerb weight	1590 kg
Max. allowed weight	2030 kg
Additional information	

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/1