





report date: 2024-03-28

General information

Make	FIAT
Model	PANDA POP
Colour	Red
Year of manufacture	2016
Top speed	102 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-02-21

Pictures 10

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/13



HF66KUD report date: 2024-03-28

MOT history

MOT expiry date	2024-10-12
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	31
Total items failed	2

MOT #7		2023-10-07 09:32
MOT test	number	907286742069
Result		✓ Passed
Next expi	ry date	2024-10-12
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Front Daytime running light not working	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3 mm & Very w	vorn inner edge (5.2.3 (e))
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice	Slight corrosion underside of vehicle.	
Advice	Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice (e))	Nearside Front Tyre worn close to legal limit/worn on edge 2 mm & Very	worn inner edge (5.2.3

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #6 2023-10-07 09:32 265130397882 **MOT** test number Result **★** Failed **Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Front Tyre worn close to legal limit/worn on edge 3 mm & Very worn inner edge (5.2.3 (e)) Advice Offside Rear Service brake binding but not excessively (1.2.1 (f)) Advice Slight corrosion underside of vehicle. **Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2 mm & Very worn inner edge (5.2.3 (e)Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c)) Advice Offside Front Daytime running light not working Advice

MOT #5		2022-10-13 10:53
MOT test	number	294111343022
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Slight corrosion: Exhaust	
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #4 2021-09-29 08:48 **MOT** test number 260587320494 Result ✓ Passed Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) **Advice** Offside Play in steering rack inner joint(s) **Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Slight corrosion; Exhaust **Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #3 2021-09-29 08:48 **MOT** test number 335279835074 Result **X** Failed Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b)) Advice Slight corrosion; Exhaust Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Play in steering rack inner joint(s) **Advice Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #2

MOT test number

455707486080

Result

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Play in steering rack inner joint(s)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2019-09-05 08:15

MOT test number 707406927699

Result ✓ Passed

CarCheck.co.uk page 6/13



HF66KUD report date: 2024-03-28

Toport dato: 202

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
HARMAN CO.	

THE STATE OF THE S	
HEREERS	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-10-18
Last registration	2023-10-07
Complete history	See info



Registration #1	2016-10-18	9 mi
Registration #2	2019-09-05	20.577 mi
Registration #3	2020-10-08	22.978 mi
Registration #4		11.777 es
Registration #5	2021-09-29	30.235 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1882 mm
Height	1551 mm
Length	3653 mm
Wheel base	2300 mm
Kerb weight	1015 kg
Max. allowed weight	1420 kg

Additional information

Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats	4	
Engine number Carcheck.co.uk	1523903	page 13/13