





report date: 2024-03-28

General information

| Make | FIAT |
|---------------------|---------------------------|
| Model | BRAVO ACTIVE 120 MULTIJET |
| Colour | Blue |
| Year of manufacture | - |
| Top speed | 120 mph |
| 0 - 60 mph | 10.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 120 BHP |
|-------------------------|---------------------|
| Max. torque | 255 Nm at 2.000 rpm |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 40.9 mpg |
| Consumption extra urban | 65.7 mpg |
| Consumption combined | 53.3 mpg |



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

| _ | | | | _ | - |
|---|---|---|----|---|---|
| - | n | т | rv | , | |
| | | | | | |

| Elitiy 1 | |
|---------------|-------------|
| Date | 2021-09-18 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT #19 2023-06-19 12:32

MOT test number 437207290987

Result X Failed

Fail Hydraulic brake cylinder has no reserve travel and braking performance affected (1.1.16 (e) (ii))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail Offside Front Service brake effort inadequate at a wheel (1.2.1 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

Advice Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))

Fail Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen washer not working (3.5 (a))

MOT #18 2022-06-20 10:43

MOT test number 470472112080

Result \rightarrow Passed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #17 2022-06-17 13:41

MOT test number 471361034308

Result X Failed

Fail Offside Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Sun visor (3.1 (a) (ii))

Advice Nearside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Front Windscreen washer not working (3.5 (a))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #16 2021-09-24 15:09

MOT test number 940701343364

Result

Passed

MOT #15 2021-08-28 13:47

MOT test number 616866932300

Result × Failed

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength outer sill (5.3.6 (a) (i))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

CarCheck.co.uk page 4/13



report date: 2024-03-28

✓ Passed

 MOT #14
 2020-09-01 10:43

 MOT test number
 512584125872

 Result
 ✓ Passed

 MOT #13
 2019-10-25 14:26

MOT test number 685461590389

Result ✓ Passed

Advice Under trays fitted

Result

MOT #12 2018-10-29 10:54 MOT test number 466089344938

MOT #11 2018-10-29 10:54

MOT test number 488451662589

Result ★ Failed

Pass with rectification Windscreen washer not working (3.5 (a))

MOT #10 2017-09-12 14:51

MOT test number 983534958464

Result \(\sqrt{Passed} \)

Advice Front brake disc worn, pitted or scored, but not seriously weakened both sides inner face slightly (3.5.1i)

Advice Exhaust has a minor leak of exhaust gases outer skin coming off (7.1.2)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1)

MOT #8 2016-09-19 12:11 **MOT** test number 204951644627 Result × Failed Pass with rectification Offside Front Windscreen washer provides insufficient washer liquid (8.2.3) Pass with rectification Nearside Rear position lamp(s) not working (1.1.A.3b) **Advice** Nearside Front Tyre worn close to the legal limit outer edge (4.1.E.1) Advice Parking brake lever has little reserve travel (3.1.6b) Pass with rectification Nearside Stop lamp adversely affected by the operation of another lamp (1.2.1f) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7

MOT test number

478402445167

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #6
 2014-05-21 11:15

 MOT test number
 678771144199

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

X Failed

 MOT #5
 2013-04-02 15:13

 MOT test number
 798662393065

MOT #4 2012-12-05 13:23

MOT test number 738890442373

Result

Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2012-12-05 12:20

MOT test number 755910642331

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Exhaust emits an excessive level of metered smoke (7.4.B.3a)

MOT #2 2011-12-09 14:10

MOT test number 159843141303

Result ✓ Passed

MOT #1 2011-12-09 14:10

MOT test number 376303241397

5703352.1337

Pass with rectification Offside Headlamp aim too low (1.8)

Result

Pass with rectification Nearside Headlamp aim too low (1.8)

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



faste since

WN58AOX

report date: 2024-03-28

More info >

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this FIAT had different number plates.

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 20 |
| First mileage registration | 2008-09-26 |
| Last registration | 2023-06-19 |
| Complete history | See info |



| 2008-09-26 | 24 mi |
|------------|--|
| 2011-12-09 | 24.774 mi |
| 2012-12-05 | 32.924 mi |
| 2012-12-05 | 32.930 mi |
| 2013-04-02 | 35.855 mi |
| 2014-05-21 | 41.087 mi |
| 2015-05-22 | 46.576 mi |
| 2016-09-19 | 53.284 mi |
| 2016-09-19 | 53.284 mi |
| 2017-09-12 | 64.653 mi |
| | 9.70 es |
| | 71.777 es |
| | 9.70 es |
| | 71.777 es |
| | 9.70 es |
| | 71.777 es |
| | 9.70 es |
| | 11.777 es |
| | 11.777 es |
| | |
| | 2011-12-09 2012-12-05 2012-12-05 2013-04-02 2014-05-21 2015-05-22 2016-09-19 2016-09-19 2017-09-12 |

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 0566 | |
| 60567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1792 mm |
|---------------------|---------|
| Height | 1498 mm |
| Length | 4336 mm |
| Wheel base | 2600 mm |
| Kerb weight | 1320 kg |
| Max. allowed weight | 1830 kg |

Additional information

| · · · · · · · · · · · · · · · · · · · | |
|---------------------------------------|------------------|
| Fuel tank capacity | 58 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 13/13 |