



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Beige
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I





MOT history

MOT expiry date	2024-09-25
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	44
Total items failed	18

MOT #19	2023-09-26 13:56
MOT test number	295095595724
Result	✓ Passed
Next expiry date	2024-09-25
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material to rear by front subframe (1.1.11 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Exhaust has a minor leak of exhaust gases both central join and rear join (6.1.2 (a))

**MOT #18**

2023-09-25 15:11

MOT test number

990100449149

Result**✗ Failed****MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material to rear by front subframe (1.1.11 (c))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Front passenger door cannot be opened from outside the vehicle (6.2.3 (a))**MAJOR** Nearside Rear Position lamp light intensity significantly reduced (4.2.3 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases both central join and rear join (6.1.2 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #17**

2020-06-30 11:13

MOT test number

857913860568

Result**✓ Passed****Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**MOT #16**

2020-06-30 11:13

MOT test number

349375161627

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15

2019-03-27 14:07

MOT test number

647177946386

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))

MOT #14

2018-03-28 14:02

MOT test number

504719663337

Result**✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #13**

2018-03-22 12:35

MOT test number

746328595281

Result

✗ Failed

Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front passenger door cannot be opened from outside the vehicle (6.2.B.1b)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #12**

2017-03-17 10:52

MOT test number

173563123997

Result

✓ Passed

Advice Sill covers fitted obscuring some components**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**MOT #11**

2017-03-16 16:18

MOT test number

290052470124

Result

✗ Failed

Advice Nearside Front Tyre worn close to the legal limit inside edge (4.1.E.1)**Fail** Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Brake pipe excessively corroded front to rear (3.6.B.2c)**Advice** Sill covers fitted obscuring some components**Fail** Fuel system component leaking fuel filter (7.2.3)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Brake pipe excessively corroded front to rear (3.6.B.2c)

**MOT #10** 2016-04-15 14:55**MOT test number** 762804136254**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-04-15 08:11**MOT test number** 875049767535**Result** ✗ Failed**Fail** Nearside Rear Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Passenger's seat insecure (6.2.A.1)**Fail** Offside Rear Rear position lamp(s) not working (1.1.A.3b)**Fail** Centre Rear Exhaust system not adequately supported (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-04-15 09:05**MOT test number** 328295105155**Result** ✓ Passed**MOT #7** 2015-04-15 09:05**MOT test number** 229865405425**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2014-03-14 14:34**MOT test number** 896973574077**Result** ✓ Passed**MOT #5** 2014-03-14 13:28**MOT test number** 159973874449**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**MOT #4** 2013-03-18 09:07**MOT test number** 205057873043**Result** ✓ Passed**MOT #3** 2012-03-09 13:21**MOT test number** 316439062006**Result** ✓ Passed**Notice** Exhaust centre pipe mounting corroded**MOT #2** 2011-03-10 12:50**MOT test number** 198239061485**Result** ✓ Passed**MOT #1** 2011-03-09 13:18**MOT test number** 138498361007**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
25 September 2024

Tax status	Valid until 1 December
Days left	217
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	NU08GXA
Plate since	2019-06-29
Current registration	NU08GXA
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-03-13
Last registration	2023-09-26
Complete history	See info



Registration #1	2008-03-13	16 mi
Registration #2	2011-03-09	41.150 mi
Registration #3	2011-03-10	41.150 mi
Registration #4	2012-03-09	53.710 mi
Registration #5	2013-03-18	62.992 mi
Registration #6	2014-03-14	72.863 mi
Registration #7	2014-03-14	72.863 mi
Registration #8	2015-04-15	80.468 mi
Registration #9	2016-04-15	95.724 mi
Registration #10	2016-04-15	95.724 mi
Registration #11	2016-04-15	95.724 mi
Registration #12	2016-04-15	95.724 mi
Registration #13	2016-04-15	95.724 mi
Registration #14	2016-04-15	95.724 mi
Registration #15	2016-04-15	95.724 mi
Registration #16	2016-04-15	95.724 mi
Registration #17	2016-04-15	95.724 mi
Registration #18	2016-04-15	95.724 mi
Registration #19	2016-04-15	95.724 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295