



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Beige
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I





Internet history

Entry 2


Date	2023-02-02
Pictures	50
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2022-02-12
Pictures	42
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-15
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	28
Total items failed	6

**MOT #17**

2024-02-05 11:38

MOT test number

315913780681

Result

✓ Passed

Next expiry date

2025-02-15

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge slightly worn (5.2.3 (e))
- Minor** Nearside Rear Inner Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Minor** Offside Front Headlamp lens slightly defective slightly deteriorated (4.1.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged inner wall slight tear (5.2.3 (d) (ii))
- Advice** Nearside Front Coil spring corroded slightly corroded (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))
- Advice** Nearside Rear Coil spring corroded slightly corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge slightly worn (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge slightly worn (5.2.3 (e))
- Minor** Nearside Front Headlamp lens slightly defective slightly deteriorated (4.1.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly corroded (1.1.14 (a) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened slightly corroded (5.3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing slightly perished (5.2.3 (d) (ii))
- Advice** Offside Front Coil spring corroded slightly corroded (5.3.1 (b) (i))
- Advice** Unable to fully inspect due to covers and shields
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge slightly worn (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded slightly corroded (5.3.1 (b) (i))

MOT #16

2023-02-02 13:57

MOT test number

597955194363

Result

✓ Passed

**MOT #15** 2022-02-16 08:39**MOT test number** 858117793737**Result** ✓ Passed**MOT #14** 2021-04-13 08:46**MOT test number** 646147031123**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view in zone b (3.2 (a) (i))**MOT #13** 2020-04-22 13:25**MOT test number** 256065566289**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2020-04-18 11:51**MOT test number** 519444772308**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Fuel system component leaking fuel filter (6.1.3 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Brake pipe excessively corroded both front to rear (1.1.11 (c))**MOT #11** 2019-04-05 09:57**MOT test number** 880461255924**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10** 2019-04-04 08:45**MOT test number** 645628877346**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #9** 2018-04-06 13:04**MOT test number** 973236769268**Result** ✓ Passed**Advice** Exhaust front flexie pipe deteriorated**MOT #8** 2017-04-05 15:50**MOT test number** 862428638409**Result** ✓ Passed**MOT #7** 2016-03-31 16:08**MOT test number** 576292534777**Result** ✓ Passed**MOT #6** 2015-03-25 15:51**MOT test number** 649684585078**Result** ✓ Passed**MOT #5** 2015-03-20 10:04**MOT test number** 635239275053**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Fail** Offside Front coil spring broken (2.4.C.1a)



MOT #4	2014-04-03 16:34
MOT test number	956583994055
Result	✓ Passed
MOT #3	2013-02-28 11:06
MOT test number	387489553035
Result	✓ Passed
Advice	Tyre worn close to the legal limit (4.1.E.1)
MOT #2	2012-03-02 16:14
MOT test number	405052362030
Result	✓ Passed
Notice	N/s steering arm has slight play
MOT #1	2011-03-01 18:26
MOT test number	118260461447
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-02-19
Last registration	2024-02-05
Complete history	See info



Registration #1	2008-02-19	9 mi
Registration #2	2011-03-01	27.384 mi
Registration #3	2012-03-02	34.352 mi
Registration #4	2013-02-28	41.458 mi
Registration #5	2014-04-03	47.912 mi
Registration #6	2015-03-20	54.964 mi
Registration #7	2015-03-25	54.997 mi
Registration #8	2016-03-31	60.699 mi
Registration #9	2017-04-05	65.858 mi
Registration #10	2018-04-06	72.538 mi
Registration #11	2019-04-06	79.218 mi
Registration #12	2020-04-06	85.898 mi
Registration #13	2021-04-06	92.578 mi
Registration #14	2022-04-06	99.258 mi
Registration #15	2023-04-06	105.938 mi
Registration #16	2024-02-05	112.618 mi
Registration #17	2024-02-05	112.618 mi
Registration #18	2024-02-05	112.618 mi
Registration #19	2024-02-05	112.618 mi
Registration #20	2024-02-05	112.618 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295