



EK09HSO

report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Black
Year of manufacture	2009
Top speed	137 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	360 Nm at 1.800 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





MOT history

MOT expiry date	2024-05-23
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	23
Total items failed	6

MOT #11	2023-05-24 15:49
---------	------------------

MOT test number	558609886708
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-05-23
------------------	------------

- Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice Offside Rear Tyre slightly damaged/cracking or perishing inner edge (5.2.3 (d) (ii))
- Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #10**

2023-05-12 08:30

MOT test number

334311197745

Result**✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Headlamp aim too far to the right (4.1.2 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing inner edge (5.2.3 (d) (ii))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

MOT #9

2022-05-11 15:43

MOT test number

578423680069

Result**✓ Passed**

- Advice** Unable to fully inspect underside due to underseal

MOT #8

2020-01-06 09:43

MOT test number

756460420774

Result**✓ Passed**

**MOT #7** 2018-12-27 14:46**MOT test number** 742127377501**Result** ✓ Passed**Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))**Advice** Engine covers and Undertrays fitted obscuring view of components**MOT #6** 2017-10-20 16:02**MOT test number** 824928764503**Result** ✓ Passed**MOT #5** 2016-06-23 16:22**MOT test number** 825240196324**Result** ✓ Passed**MOT #4** 2016-06-22 15:27**MOT test number** 384664817485**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened li (3.5.1i)**MOT #3** 2014-06-16 09:36**MOT test number** 715627864136**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



MOT #2	2013-05-18 10:58
MOT test number	258328633129
Result	✓ Passed
MOT #1	2012-06-26 09:28
MOT test number	207128372190
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
23 May 2024

Tax status	Valid until 1 May
Days left	2
MOT expiry date	23 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	EK09HSO
Plate since	2019-09-28
Current registration	EK09HSO
Plate since	2019-09-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-04-16
Last registration	2023-05-24
Complete history	See info



Registration #1	2009-04-16	7 mi
Registration #2	2012-06-26	34.160 mi
Registration #3	2013-05-18	45.609 mi
Registration #4	2014-06-16	56.918 mi
Registration #5	2016-06-22	60.274 mi
Registration #6	2016-06-23	60.274 mi
Registration #7	2019-05-29	75.277 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1395 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	090409201123BG