





report date: 2024-03-29

### General information

Make	HYUNDAI	
Model	IX35 GDI SE NAV BLUE DRIVE	
Colour	Black	
Year of manufacture	2015	
Top speed	111 mph	
0 - 60 mph	11.1 seconds	
Gearbox	6 speed Manual	

### Engine & fuel consumption

Power	133 BHP	
Max. torque	165 Nm at 4.800 rpm	
Engine capacity	1.591 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	37.7 mpg	
Consumption extra urban	48.7 mpg	
Consumption combined	44.1 mpg	
CO2 emission	149 g/km	
CO2 label	F	



CarCheck.co.uk page 1/11




# Internet history

### Entry 1

Date 2022-01-19


Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-17
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	9
Total items failed	4

MOT #7	2023-11-14 13:57
MOT test number	606838679269
Result	✓ Passed
Next expiry date	2024-11-17
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #6	2023-11-10 14:30
MOT test number	262636040777
Result	🗙 Failed
Fail Rear Parking brake efficiency below requirements (1.4.2 (a) (i))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
Fail Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))	
Fail Rear Service brake excessively binding (1.2.1 (f))	

MOT #5	2022-11-11 11:38
MOT test number	211809151314
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #4 2021-11-18 15:58

**MOT test number** 428216364154

**Result** ✓ Passed

MOT #3 2020-07-14 10:08

**MOT test number** 871764238619

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2 2019-04-29 10:56

**MOT test number** 278733351076

**Result** 
✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #1 2018-05-01 11:11

**MOT test number** 452248000524

CarCheck.co.uk page 4/11



## Tax & MOT check



Tax status	Valid until 1 February
Days left	279
MOT expiry date	17 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 5/11



**DV15ETO** 

report date: 2024-03-29

#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e when miscory	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
********	
************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 9/11



## Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-04-22
Last registration	2023-11-14
Complete history	See info



Registration #1	2015-04-22	26 mi
Registration #2	2018-05-01	43.926 mi
Registration #3	2019-04-29	59.927 mi
Registration #4	2020-07-14	74.099 mi
Registration #5	2021-11-18	85.942 mi
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		0.00 44
Registration #9		D.777 es

More info >

CarCheck.co.uk page 10/11



### Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

## Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



## Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1427 kg
Max. allowed weight	1830 kg

# Additional information

Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11