




report date: 2024-03-28

General information

Make	FIAT
Model	QUBO MULTIJET MYLIFE
Colour	Black
Year of manufacture	2012
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	78.5 mpg
Consumption combined	68.9 mpg
CO2 emission	107 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	20
Total items failed	16

MOT #14 2023-05-31 07:51

MOT test number 134852194322

Result ✓ Passed

Next expiry date 2024-06-01

Advice Oil leak, but not excessive from gearbox (8.4.1 (a) (i))**Advice** Offside headlamp beam pattern only just achieved

MOT #13 2023-05-26 14:28

MOT test number 588411173402

Result ✗ Failed**Advice** Oil leak, but not excessive from gearbox (8.4.1 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside headlamp beam pattern only just achieved**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #12 2022-05-30 14:56

MOT test number 296669105028

Result ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11**

2022-05-30 10:40

MOT test number

246726969528

Result**✗ Failed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

MOT #10

2021-06-01 12:12

MOT test number

755775582452

Result**✓ Passed**

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2020-06-02 12:01

MOT test number

939868300626

Result**✓ Passed****MOT #8**

2019-09-09 15:06

MOT test number

788033446838

Result**✓ Passed**

**MOT #7** 2018-09-07 13:02**MOT test number** 807369539639**Result** ✓ Passed**Advice** Oil lamp flashing**MOT #6** 2018-09-06 09:58**MOT test number** 652080437357**Result** ✗ Failed**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Oil lamp flashing**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp aim too low (4.1.2 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Offside Front Tyre has ply or cords exposed 195/55/16v (5.2.3 (d) (ii))**MOT #5** 2017-09-04 14:25**MOT test number** 128278975544**Result** ✓ Passed**Advice** Oil lamp and EML on**MOT #4** 2017-09-04 10:04**MOT test number** 983979409389**Result** ✗ Failed**Advice** Oil lamp and EML on**Fail** Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)



MOT #3	2016-09-01 12:55
MOT test number	563221302868
Result	✓ Passed

MOT #2	2016-09-01 08:34
MOT test number	305589475934
Result	✗ Failed
Fail	Brake pedal anti-slip provision missing (3.3.A.1b)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2015-09-08 09:05
MOT test number	517074297549
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	EY62KNA
Plate since	2019-09-28
Current registration	EY62KNA
Plate since	2019-09-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-09-01
Last registration	2023-05-31
Complete history	See info



Registration #1	2012-09-01	9 mi
Registration #2	2015-09-08	37.284 mi
Registration #3	2016-09-01	50.925 mi
Registration #4	2016-09-01	50.925 mi
Registration #5	2017-09-04	65.664 mi
Registration #6	2017-09-04	65.664 mi
Registration #7	2018-09-06	74.514 mi
Registration #8	2018-09-07	74.514 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2023-05-31	75.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1716 mm
Height	1721 mm
Length	3595 mm
Wheel base	2513 mm
Kerb weight	1180 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	4765494