




report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.8 mpg
CO2 emission	208 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-06-10
Pictures	50
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-06-09
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	12
Total items failed	9

MOT #12	2023-06-07 08:46
MOT test number	781328043066
Result	✓ Passed
Next expiry date	2024-06-09
<b>Advice</b>	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #11	2022-06-10 12:32
MOT test number	161501916684
Result	✓ Passed

MOT #10	2021-10-25 14:37
MOT test number	296760926278
Result	✓ Passed
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2021-10-23 10:42
MOT test number	612625772873
Result	✗ Failed
<b>Fail</b>	Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2020-09-23 15:58**MOT test number** 261180885171**Result** ✓ Passed**MOT #7** 2020-09-22 11:09**MOT test number** 250640981005**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2019-09-13 13:54**MOT test number** 180491974944**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Oil leak, but not excessive engine oil on chassis leg not dripping (8.4.1 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #5** 2019-09-10 08:58**MOT test number** 861034239473**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Oil leak, but not excessive engine oil on chassis leg not dripping (8.4.1 (a) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #4** 2018-06-28 08:03**MOT test number** 566925892141**Result** ✓ Passed**MOT #3** 2016-12-14 09:05**MOT test number** 108089418195**Result** ✓ Passed**MOT #2** 2015-12-21 14:04**MOT test number** 902386590057**Result** ✓ Passed**MOT #1** 2015-12-21 12:28**MOT test number** 369759292011**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
9 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	9 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	<b>GV62NTM</b>
Plate since	2019-03-29
Current registration	<b>GV62NTM</b>
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-02-14
Last registration	2023-06-07
Complete history	<a href="#">See info</a>



Registration #1	2013-02-14	22 mi
Registration #2	2015-12-21	41.781 mi
Registration #3	2015-12-21	41.781 mi
Registration #4	2016-12-14	62.429 mi
Registration #5	2018-06-28	76.364 mi
Registration #6	2019-09-10	77.445 mi
Registration #7	2019-09-13	77.445 mi
Registration #8	2019-09-13	77.445 mi
Registration #9	2019-09-13	77.445 mi
Registration #10	2019-09-13	77.445 mi
Registration #11	2019-09-13	77.445 mi
Registration #12	2019-09-13	77.445 mi
Registration #13	2019-09-13	77.445 mi
Registration #14	2019-09-13	77.445 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	227236K