



RENAULT

Y256MJM

report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO RXE
Colour	Silver
Year of manufacture	2001
Top speed	89 mph
0 - 60 mph	14.3 seconds
Gearbox	3 speed automatic

Engine & fuel consumption

Power	74 BHP
Max. torque	114 Nm at 4.250 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.8 mpg
CO2 emission	188 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-01-21
Pictures	9
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-04-20
MOT pass rate	76 %
MOT passed	19
Failed MOT tests	6
Total advice items	25
Total items failed	15

MOT #25	2024-03-27 13:43
MOT test number	554424108166
Result	✓ Passed
Next expiry date	2025-04-20
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Advice	Rear Exhaust mounting defective mounting rubbers perished (6.1.2 (a))
Advice	Nearside Non obligatory mirror damaged

**MOT #24**

2024-03-26 10:23

MOT test number

567191271335

Result**✗ Failed**

- Advice** Nearside Non obligatory mirror damaged
- Fail** All direction indicators not working (4.4.1 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear Passenger seat(s) missing at time of test
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Rear Exhaust mounting defective mounting rubbers perished (6.1.2 (a))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Offside Rear Seat belt anchorage prescribed area strength or continuity significantly reduced wheelchair (7.1.1 (a) (i))

MOT #23

2023-04-17 09:56

MOT test number

836073177156

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

MOT #22

2023-04-17 08:57

MOT test number

882906751987

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

MOT #21

2022-04-21 09:44

MOT test number

391619062586

Result**✓ Passed**

**MOT #20**

2022-04-21 09:44

MOT test number

119550290088

Result**✗ Failed****Pass with rectification**

Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

MOT #19

2021-03-02 15:51

MOT test number

196534212030

Result**✓ Passed****Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Minor

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice

Nearside Non obligatory mirror damaged

Advice

Offside Front Anti-lock braking system component slightly damaged ABS RING CRACKED (1.6 (e))

MOT #18

2021-03-01 09:04

MOT test number

467592479151

Result**✗ Failed****Fail**

Nearside Rear Service brake excessively binding (1.2.1 (f))

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Nearside Non obligatory mirror damaged

Advice

Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))

Minor

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Advice

Offside Front Anti-lock braking system component slightly damaged ABS RING CRACKED (1.6 (e))

**MOT #17** 2020-02-20 14:45**MOT test number** 306705036864**Result** ✓ Passed**Minor** Hazard warning switch faulty (4.4.2 (a) (i))**Advice** Nearside Non obligatory mirror damaged**MOT #16** 2019-02-21 14:15**MOT test number** 679234794155**Result** ✓ Passed**MOT #15** 2019-02-20 11:23**MOT test number** 663822499021**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Front Anti-lock braking system component excessively damaged sensor ring (1.6 (e))**Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #14** 2018-02-19 13:28**MOT test number** 954140193853**Result** ✓ Passed

**MOT #13** 2017-02-21 13:35**MOT test number** 843348146315**Result** ✓ Passed**Advice** Nearside Front Steering rack gaiter deteriorated (2.2.D.2d)**MOT #12** 2016-02-17 16:08**MOT test number** 145781456849**Result** ✓ Passed**MOT #11** 2015-02-24 12:24**MOT test number** 416505355079**Result** ✓ Passed**MOT #10** 2014-02-25 12:09**MOT test number** 458556054048**Result** ✓ Passed**MOT #9** 2014-02-25 12:09**MOT test number** 738566354034**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2013-02-27 13:29**MOT test number** 666148553064**Result** ✓ Passed**Notice** N/s/r brake binding slightly**MOT #7** 2012-02-21 10:25**MOT test number** 149312952004**Result** ✓ Passed



MOT #6	2011-03-01 15:11
---------------	------------------

MOT test number	646230761098
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-03-09 11:19
---------------	------------------

MOT test number	671298260021
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-04-28 15:37
---------------	------------------

MOT test number	980788819145
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-04-22 12:58
---------------	------------------

MOT test number	140613818143
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-04-30 15:24
---------------	------------------

MOT test number	560260027189
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-04-26 11:55
---------------	------------------

MOT test number	261808316120
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
---------------	--



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
20 April 2025

Tax status	Valid until 1 May
Days left	3
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	Y256MJM
Plate since	2024-03-28
Current registration	Y256MJM
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	0123 456789

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-03-22
Last registration	2024-03-27
Complete history	See info



Registration #1	2001-03-22	16 mi
Registration #2	2006-04-26	25.659 mi
Registration #3	2007-04-30	28.542 mi
Registration #4	2008-04-22	30.059 mi
Registration #5	2009-04-28	33.414 mi
Registration #6	2010-03-09	36.259 mi
Registration #7	2011-03-01	39.529 mi
Registration #8	2012-02-21	42.624 mi
Registration #9	2013-02-27	45.269 mi
Registration #10	2014-02-25	47.940 mi
Registration #11	2015-02-24	50.210 mi
Registration #12	2016-02-17	52.539 mi
Registration #13	2017-02-21	54.417 mi
Registration #14	2018-03-20	56.300 mi
Registration #15	2019-03-20	58.183 mi
Registration #16	2020-03-20	60.066 mi
Registration #17	2021-03-20	61.949 mi
Registration #18	2022-03-20	63.832 mi
Registration #19	2023-03-20	65.715 mi
Registration #20	2024-03-20	67.598 mi
Registration #21	2025-03-20	69.481 mi
Registration #22	2026-03-20	71.364 mi
Registration #23	2027-03-20	73.247 mi
Registration #24	2028-03-20	75.130 mi
Registration #25	2029-03-20	77.013 mi
Registration #26	2030-03-20	78.896 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2060 mm
Height	1827 mm
Length	3995 mm
Wheel base	2600 mm
Kerb weight	1065 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	R001355