



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS C-MAX TITANIUM D
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	51.4 mpg





LABEL UNKNOWN



Internet history

Entry 2

Date	2021-09-25
Pictures	50
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-24
Pictures	0
Listing price	View report

source: autotrader.co.uk

**MOT history****MOT #21**

2022-09-26 11:11

MOT test number

791432020792

Result**✗ Failed**

- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Headlamp light intensity severely reduced (4.1.4 (a))
- Advice** Offside Rear Seat belt anchorage prescribed area is corroded but not considered excessive sill (7.1.1 (a) (i))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20** 2021-09-28 09:43**MOT test number** 533610294195**Result** ✓ Passed**MOT #19** 2021-09-27 18:46**MOT test number** 730009875456**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #18** 2020-09-14 16:20**MOT test number** 684319025781**Result** ✓ Passed**Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))**Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))**MOT #17** 2019-09-16 15:04**MOT test number** 115229495396**Result** ✓ Passed**MOT #16** 2019-09-16 07:55**MOT test number** 497665264159**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Brake pad(s) wearing thin 2mm (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #15** 2018-09-25 10:12**MOT test number** 402997044201**Result** ✓ Passed**MOT #14** 2017-09-25 14:36**MOT test number** 919286211276**Result** ✓ Passed**Advice** Rear exhaust mount broken**Advice** Nearside Rear Nail in tyre**Advice** N/s/f tyre worn to limit bald on outer edge**MOT #13** 2017-06-28 09:09**MOT test number** 818745894839**Result** ✓ Passed**Advice** N/s/f tyre bald on outer edge**MOT #12** 2017-06-27 08:22**MOT test number** 391666112904**Result** ✗ Failed**Advice** N/s/f tyre bald on outer edge**Fail** Headlamp excessively deteriorated so that the light output is severely reduced n/s and o/s (1.7.5a)**MOT #11** 2016-05-09 10:55**MOT test number** 165272437393**Result** ✓ Passed**Advice** Headlamp deteriorated but light output not reduced both (1.7.5a)

**MOT #10** 2015-05-11 09:35**MOT test number** 218921535444**Result** ✓ Passed**Advice** Headlamp deteriorated but light output not reduced (1.7.5a)**Notice** Rear brake pads worn to limit**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #9** 2014-05-16 16:35**MOT test number** 956646934165**Result** ✓ Passed**MOT #8** 2014-05-15 12:54**MOT test number** 666415534194**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Lower Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)**MOT #7** 2013-06-06 13:55**MOT test number** 799727353190**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6** 2012-06-08 09:34**MOT test number** 389930062190**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2011-05-31 09:10**MOT test number** 786141351116**Result** ✓ Passed**MOT #4** 2010-05-29 10:02**MOT test number** 193969340181**Result** ✓ Passed**MOT #3** 2009-05-30 09:54**MOT test number** 612660159189**Result** ✓ Passed**MOT #2** 2009-05-30 09:54**MOT test number** 540890559164**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #1** 2008-05-30 10:16**MOT test number** 460521458148**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	 XXXXX
Plate since	2019-06-29
Current registration	 XXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-06-08
Last registration	2022-09-26
Complete history	See info



Registration #1	2005-06-08	11 mi
Registration #2	2008-05-30	14.443 mi
Registration #3	2009-05-30	20.013 mi
Registration #4	2010-05-29	28.325 mi
Registration #5	2011-05-31	35.420 mi
Registration #6	2012-06-08	41.975 mi
Registration #7	2013-06-06	48.921 mi
Registration #8	2014-05-15	54.827 mi
Registration #9	2014-05-16	54.839 mi
Registration #10	2015-05-11	65.438 mi
Registration #11	2016-05-09	74.908 mi
Registration #12	2017-06-27	87.271 mi
Registration #13	2018-06-27	95.277 mi
Registration #14	2019-06-27	103.283 mi
Registration #15	2020-06-27	111.289 mi
Registration #16	2021-06-27	119.295 mi
Registration #17	2022-06-27	127.301 mi
Registration #18	2023-06-27	135.307 mi
Registration #19	2024-06-27	143.313 mi
Registration #20	2025-06-27	151.319 mi
Registration #21	2026-06-27	159.325 mi
Registration #22	2027-06-27	167.331 mi
Registration #23	2028-06-27	175.337 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4382 mm
Wheel base	2640 mm
Kerb weight	1276 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Engine number

5U29666