





report date: 2024-03-28

### General information

| Make                | PEUGEOT                |  |
|---------------------|------------------------|--|
| Model               | 508 BLUEHDI S/S ALLURE |  |
| Colour              | Blue                   |  |
| Year of manufacture | 2019                   |  |
| Top speed           | 129 mph                |  |
| Gearbox             | 6 speed Manual         |  |

## Engine & fuel consumption

| Power                | 129 BHP             |
|----------------------|---------------------|
| Max. torque          | 300 Nm at 1.750 rpm |
| Engine capacity      | 1.500 cc            |
| Cylinders            | 4                   |
| Fuel type            | Diesel              |
| Consumption combined | 60.1 mpg            |
| CO2 emission         | 104 g/km            |
| CO2 label            | В                   |



CarCheck.co.uk page 1/10



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2021-08-14

Pictures 34

Listing price <u>View report</u>









source: heycar.co.uk

Entry 1

Date 2021-08-06

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



KU19HAH
report date: 2024-03-28

MOT history

| MOT expiry date    | 2024-07-03 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 2          |
| Failed MOT tests   | 1          |
| Total advice items | 0          |
| Total items failed | 4          |

| MOT #3           | 2023-06-20 15:43 |
|------------------|------------------|
| MOT test number  | 638353881236     |
| Result           | <b>✓</b> Passed  |
| Next expiry date | 2024-07-03       |

| MOT #2 | 2   | 2023-06-20 09:39   |
|--------|---|--------------------|
| MOT te | st number   | 871373032914       |
| Result |   | <b>X</b> Failed    |
| Fail   | Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))       |                    |
| Fail   | Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))            |                    |
| Fail   | Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) |                    |
| Fail   | Offside Front Tyre has a bulge, caused by separation or partial failure of its structur | e (5.2.3 (d) (ii)) |

| MOT #1          | 2022-06-10 12:13 |
|-----------------|------------------|
| MOT test number | 631000319643     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/10



KU19HAH
report date: 2024-03-28

### Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 94                   |
| MOT expiry date  | 3 July 2024          |
| Full MOT history | See MOT history      |

### Tax calculation

| Vehicle class  | 49         |
|--|------------|
| Band   | F          |
| First licence fee (12 months)                        | £ 185,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 210,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/10



report date: 2024-03-28

### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



KU19HAH report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-28

# Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is |             |
|---|-------------|
| ***************************************   |             |
| ***************************************   |             |
| ***************************************   |             |
| ********  |             |
|   |             |
| ***************************************   |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this PEUGEOT had different number plates.  |             |
| Number of plates  | ,           |
| Current registration  | NK SIK      |
| Plate since   |             |
| Current registration  | NK SIN      |
| Plate since   |             |
|   | More info > |

CarCheck.co.uk page 7/10



KU19HAH report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-28

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 6          |
| First mileage registration | 2019-07-04 |
| Last registration          | 2023-06-20 |
| Complete history           | See info   |



| Registration #1 | 2019-07-04 | 8 mi      |
|-----------------|------------|-----------|
| Registration #2 |            | 77,777 66 |
| Registration #3 |            | 11.777 es |
| Registration #4 |            | 71.777 66 |
| Registration #5 |            | 9.77 sc   |
| Posistration #6 |            |           |

Registration #6

More info >

CarCheck.co.uk page 9/10



KU19HAH report date: 2024-03-28

Car features

| 50225 | Air conditionin |
|-------|-----------------|
| 50295 |                 |
| 50482 |                 |
| 50501 |                 |
| 50566 |                 |
| 50567 |                 |
| 50569 |                 |

## Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 96%             |
| Children       | 86%             |
| Pedestrian     | 71%             |
| Safety systems | 79%             |
| Overall rating | 85%             |
| Video          | see crash video |



## Dimensions & weight

| Width               | 1859 mm |
|---------------------|---------|
| Height              | 1403 mm |
| Length              | 4750 mm |
| Max. allowed weight | 1999 kg |

## Additional information

| Number of seats | 5           |
|-----------------|-------------|
| Number of axles | 2           |
| Engine number   | Q3AM0045042 |

CarCheck.co.uk page 10/10