





report date: 2024-03-29

General information

Make	MAZDA
Model	CX-7 D SPORT TECH
Colour	Silver
Year of manufacture	2009
Top speed	124 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.184 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	42.8 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-06-16

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-06-01
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	1

MOT #17	2023-05-20 09:43
MOT test number	838057938643
Result	✓ Passed
Next expiry date	2024-06-01

MOT #16	2022-05-18 13:46
MOT test number	438681594808
Result	✓ Passed

MOT #15		2022-05-18 10:01
MOT test	number	191254100766
Result		X Failed
MAJOR	Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #14	2021-05-26 15:47
MOT test number	224408445643
Result	✓ Passed
Advice Engine knocking	

CarCheck.co.uk page 3/13



MOT #13 2021-05-26 10:15

MOT test number 778619016584

Result X Failed

Advice Engine knocking

MAJOR Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MAJOR Headlamp aim too low (4.1.2 (a))

MOT #12 2020-06-02 08:34

MOT test number 421563949096

Result ✓ Passed

MOT #11 2019-05-22 08:00

MOT test number 230696349486

Result \(\sqrt{Passed} \)

MOT #10 2018-05-29 14:42

MOT test number 238766484198

Result \(\sqrt{Passed} \)

MOT #9 2018-05-22 14:39

MOT test number 425642860045

Result × Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



Notice

Notice

HW59JJY report date: 2024-03-29

MOT #8		2017-08-24 07:37
MOT test	number	517796934133
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	All tyres are worn on inner edges close to limit	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2016-08-31 10:19
MOT test number	460823858949
Result	✓ Passed
MOT #6	2015-09-02 09:26
MOT test number	967676897153
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit 235/55x19 (4.1.E.1)	

MOT #5	2014-09-03 09:17
MOT test number	319856044239
Result	✓ Passed
MOT #4	2014-04-14 14:06
MOT test number	527104704125
Result	✓ Passed

Under-trays fitted obscuring some underside components

Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 5/13



MOT test number

Result

Notice Under-trays fitted obscuring some underside components

Fail Power steering fluid level below minimum (2.3.1)

Notice Engine covers fitted obscuring some components in the engine bay

MOT #2 2013-05-01 16:57

MOT test number 597861623144

Result ✓ Passed

MOT #1

MOT test number

419658042313

Result

Notice All four tyres wearing on inner edges

CarCheck.co.uk page 6/13





Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



_	
~	history
IMMAR	

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report here .	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-12-05
Last registration	2023-05-20
Complete history	See info



Registration #1	2009-12-05	21 mi
Registration #2	2012-12-13	19.927 mi
Registration #3	2013-05-01	20.518 mi
Registration #4	2014-04-14	30.911 mi
Registration #5	2014-04-14	30.911 mi
Registration #6	2014-09-03	33.859 mi
Registration #7	2015-09-02	42.428 mi
Registration #8	2016-08-31	53.651 mi
Registration #9	2017-08-24	65.482 mi
Registration #10	2018-05-22	73.980 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.777 es
Registration #19		D.377 es

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1870 mm
Height	1645 mm
Length	4700 mm
Wheel base	2750 mm
Kerb weight	1865 kg
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10225284

CarCheck.co.uk page 13/13