



report date: 2024-03-28

## General information

Make	VOLVO
Model	C30 D2 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-10
Pictures	24
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2025-03-27
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	24
Total items failed	3

MOT #13	2024-03-28 15:31
MOT test number	305867449796
Result	✓ Passed
Next expiry date	2025-03-27

MOT #12	2023-06-23 13:52
MOT test number	496861937685
Result	✓ Passed

MOT #11	2022-06-14 10:29
MOT test number	847533457886
Result	✓ Passed

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 205/50x17 (5.2.3 (e))

MOT #10	2022-06-11 11:02
MOT test number	312950950268

Result	✗ Failed
--------	----------

**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge 205/50x17 (5.2.3 (e))

**Fail** Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #9**

2021-06-14 15:32

**MOT test number**

449422682793

**Result**

✓ Passed

**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #8**

2021-06-11 15:47

**MOT test number**

647535245856

**Result**

✗ Failed

**Advice** Offside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Minor** Nearside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #7**

2020-11-14 16:22

**MOT test number**

302598872569

**Result**

✓ Passed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm + cracking (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**Advice** Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn to 3mm + cracking (5.2.3 (e))**MOT #6**

2019-11-16 15:06

**MOT test number**

986479828681

**Result**

✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement lower suspension arm rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))**Advice** Undertrays fitted**MOT #5**

2018-11-20 16:34

**MOT test number**

645851344659

**Result**

✓ Passed

**Advice** Undertrays fitted**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4**

2017-12-02 14:17

**MOT test number**

985014945689

**Result**

✓ Passed

**Advice** Rear tyres 3-4mm



MOT #3	2016-12-03 10:17
MOT test number	118383036953
Result	✓ Passed

MOT #2	2016-12-03 10:17
MOT test number	825859158140
Result	✗ Failed
<div>Pass with rectification</div> Nearside Registration plate lamp not working (1.1.C.1d)	

MOT #1	2015-12-05 14:34
MOT test number	260881334030
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
27 March 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	306
<b>MOT expiry date</b>	27 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>ND62VPA</b>
Plate since	2024-03-28
Current registration	<b>ND62VPA</b>
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-13
Last registration	2024-03-28
Complete history	<a href="#">See info</a>



Registration #1	2012-12-13	18 mi
Registration #2	2015-12-05	32.982 mi
Registration #3	2016-12-03	38.804 mi
Registration #4	2016-12-03	38.804 mi
Registration #5	2017-12-02	46.601 mi
Registration #6	2018-11-20	55.323 mi
Registration #7	2019-11-16	65.514 mi
Registration #8	2020-11-14	70.767 mi
Registration #9	2020-11-14	70.767 mi
Registration #10	2020-11-14	70.767 mi
Registration #11	2020-11-14	70.767 mi
Registration #12	2020-11-14	70.767 mi
Registration #13	2020-11-14	70.767 mi
Registration #14	2020-11-14	70.767 mi
Registration #15	2020-11-14	70.767 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	2259719