





report date: 2024-03-28

# General information

Make	PEUGEOT
Model	107 URBAN LITE
Colour	Silver
Year of manufacture	2011
Top speed	98 mph
0 - 60 mph	14.2 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	68 BHP
Max. torque	93 Nm at 3.600 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	52.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg
CO2 emission	103 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

#### Entry 2

Date 2021-06-27

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 1

Date	2021-06-26
Pictures	5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



OV610FK report date: 2024-03-28

MOT history

MOT expiry date	2024-07-18
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	14
Total items failed	6

MOT #13	2023-07-12 11:28
MOT test number	234841103042
Result	✓ Passed
Next expiry date	2024-07-18

MOT #12	2022-07-12 12:01
MOT test number	472350692303
Result	✓ Passed
Advice Nearside Front Suspension arm pin or bush worn but not resulting in e bush (5.3.4 (a) (i))	xcessive movement rear
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Offside Front Suspension arm pin or bush worn but not resulting in exc (5.3.4 (a) (i))	cessive movement rear bush

CarCheck.co.uk page 3/13



report date: 2024-03-28

**MOT #11** 2022-07-12 08:08

**MOT test number** 631017254135

**Result** X Failed

Fail Nearside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Fail** Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #10** 2021-07-19 10:57

**MOT test number** 285237177992

Result \rightarrow Passed

MOT #9 2021-07-19 10:07

MOT test number 806031735740

**Result** X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #8 2020-12-17 10:05

MOT test number 652580186850

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7 2019-12-19 10:02

**MOT test number** 637149831349

Result 

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

Result

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5

MOT test number

474995301295

Result

Advice Scuff mark on windscreen

MOT #4

MOT test number

Result

Advice Offside Front Outer Brake pad(s) wearing thin (3.5.1g)

MOT #3

MOT test number

Result

Advice Both rear tyres showing signs of cracking

2015-12-22 12:06

922030688176

✓ Passed

MOT #2

MOT test number

605647134354


Result

Notice Both rear tyres showing signs of cracking

CarCheck.co.uk page 5/13



report date: 2024-03-28



CarCheck.co.uk page 6/13



report date: 2024-03-28

# Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	18 July 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

## Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



OV610FK report date: 2024-03-28

Owner history

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		GEOT
*********		
***************************************		
	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-28

## Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-12-23
Last registration	2023-07-12
Complete history	See info



Registration #1	2011-12-23	23 mi
Registration #2	2014-12-02	15.899 mi
Registration #3	2014-12-03	15.899 mi
Registration #4	2015-12-22	19.106 mi
Registration #5	2016-12-21	24.098 mi
Registration #6	2017-11-27	27.876 mi
Registration #7	2018-12-14	32.538 mi
Registration #8	2019-12-19	44.514 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-28

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3430 mm
Wheel base	2340 mm
Kerb weight	900 kg
Max. allowed weight	1180 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	7010031

CarCheck.co.uk page 13/13