



report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | VOLVO |
| Model | 240 940 SET |
| Colour | Grey |
| Year of manufacture | 1991 |
| Top speed | 111 mph |
| 0 - 60 mph | 13.2 seconds |
| Gearbox | 4 speed automatic |

Engine & fuel consumption

| | |
|-----------------|---------------------|
| Power | 155 BHP |
| Max. torque | 135 Nm at 2.400 rpm |
| Engine capacity | 1.986 cc |
| Cylinders | 4 |
| Fuel type | Petrol |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-05-26 |
| Pictures | 20 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-05-18 |
| MOT pass rate | 74 % |
| MOT passed | 17 |
| Failed MOT tests | 6 |
| Total advice items | 40 |
| Total items failed | 18 |

MOT #23 2023-05-12 15:06

MOT test number 512014246867

Result ✓ Passed

Next expiry date 2024-05-18

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear brake back plates corroded

MOT #22 2022-05-19 15:50

MOT test number 515298242583

Result ✓ Passed

Minor Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Rear o/s brake back plate corroded

Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #21**

2022-05-13 09:33

MOT test number

343004635408

Result**✗ Failed****Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Offside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Fail** Nearside Rear Upper Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear o/s brake back plate corroded**MOT #20**

2021-04-14 09:47

MOT test number

562232003162

Result**✓ Passed****Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #19**

2020-05-14 07:56

MOT test number

623542956723

Result**✓ Passed****MOT #18**

2019-04-23 15:48

MOT test number

509330506368

Result**✓ Passed**

**MOT #17** 2018-01-09 12:45**MOT test number** 753986944333**Result** ✓ Passed**Advice** Front discs back plates rusty**Advice** Rear tyres worn on inside edge**MOT #16** 2016-09-08 09:28**MOT test number** 985519246801**Result** ✓ Passed**Advice** Under tray fitted**MOT #15** 2015-09-22 09:45**MOT test number** 609544319148**Result** ✓ Passed**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #14** 2014-09-29 15:36**MOT test number** 646222774268**Result** ✓ Passed**MOT #13** 2014-09-29 15:36**MOT test number** 647312774234**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**MOT #12**

2014-09-15 10:42

MOT test number

925408054232

Result**✗ Failed****Fail** Offside Stop lamp not working (1.2.1b)**Advice** Nearside Front Shock absorber has slight corrosion to the casing (2.7.2a)**Advice** Nearside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)**Notice** Centre Brake Light Inoperative**Advice** Offside Front Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #11**

2013-10-02 16:54

MOT test number

379705373453

Result**✓ Passed****Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #10** 2013-09-23 15:05**MOT test number** 306326963279**Result** ✗ Failed**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Brakes imbalanced across an axle (3.7.B.5b)**Advice** Front Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Nearside Front Headlamp aim too high (1.8)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #9** 2012-09-10 10:47**MOT test number** 696004352230**Result** ✓ Passed**MOT #8** 2011-09-26 09:22**MOT test number** 417269461284**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**MOT #7** 2010-09-08 09:26**MOT test number** 322261350435**Result** ✓ Passed**MOT #6** 2009-09-21 11:16**MOT test number** 384444669413**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Rear brake disc slightly pitted (3.5.1h)



| | |
|-----------------|------------------|
| MOT #5 | 2008-09-25 11:46 |
| MOT test number | 693989468280 |
| Result | ✓ Passed |

| | |
|--|------------------|
| MOT #4 | 2008-09-24 10:14 |
| MOT test number | 814078168270 |
| Result | ✗ Failed |
| <div><div>Fail</div> Nearside Front Seat belt stitching badly frayed (5.2.2b)</div> <div><div>Fail</div> Nearside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)</div> <div><div>Advice</div> Offside Front Seat belt stitching slightly frayed (5.2.2b)</div> <div><div>Fail</div> Nearside Front position lamp(s) not working (1.1.A.3b)</div> <div><div>Fail</div> Offside Front Headlamp not in good working order adversely affecting beam image (1.2.4a)</div> <div><div>Advice</div> Nearside Rear Seat belt stitching slightly frayed (5.2.2b)</div> | |

| | |
|---|------------------|
| MOT #3 | 2007-09-25 13:25 |
| MOT test number | 893248467252 |
| Result | ✓ Passed |
| <div><div>Notice</div> H/lamps poor pattern</div> <div><div>Notice</div> Refer also prior fail/advise</div> | |



| | |
|-----------------|--|
| MOT #2 | 2007-09-25 10:01 |
| MOT test number | 252638667230 |
| Result | ✗ Failed |
| Fail | Nearside Headlamp aim too high (1.8) |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Notice | Slight play front hub/steering area |
| Fail | Nearside Front position lamp(s) not working (1.1.A.3b) |
| Fail | Offside Headlamp aim too high (1.8) |
| Notice | N/S/R Brake binding slightly |

| | |
|-----------------|---|
| MOT #1 | 2006-09-20 10:44 |
| MOT test number | 952953866292 |
| Result | ✓ Passed |
| Advice | Offside Headlamp damaged but light output not reduced (1.7.5a) |
| Advice | Offside Front Brake hose slightly deteriorated (3.6.B.4d) |
| Advice | Nearside Headlamp damaged but light output not reduced (1.7.5a) |
| Advice | Nearside Front Brake hose slightly deteriorated (3.6.B.4d) |



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 May 2024

| | | |
|------------------|--|---------------------------------|
| Tax status | | Valid until 1 June |
| Days left | | 34 |
| MOT expiry date | | 18 May 2024 |
| Full MOT history | | See MOT history |




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|---|
| Number of plates | 1 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-29 |
| Current registration |  XXXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 1991-03-14 |
| Last registration | 2023-05-12 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 1991-03-14 | 14 mi |
| Registration #2 | 2006-09-20 | 69.477 mi |
| Registration #3 | 2007-09-25 | 71.502 mi |
| Registration #4 | 2007-09-25 | 71.502 mi |
| Registration #5 | 2008-09-24 | 73.135 mi |
| Registration #6 | 2008-09-25 | 73.143 mi |
| Registration #7 | 2009-09-21 | 74.670 mi |
| Registration #8 | 2010-09-08 | 75.602 mi |
| Registration #9 | 2011-09-26 | 76.524 mi |
| Registration #10 | 2012-09-10 | 77.576 mi |
| Registration #11 | 2013-09-23 | 79.076 mi |
| Registration #12 | 2013-10-02 | 79.142 mi |
| Registration #13 | 2013-10-02 | 79.142 mi |
| Registration #14 | 2013-10-02 | 79.142 mi |
| Registration #15 | 2013-10-02 | 79.142 mi |
| Registration #16 | 2013-10-02 | 79.142 mi |
| Registration #17 | 2013-10-02 | 79.142 mi |
| Registration #18 | 2013-10-02 | 79.142 mi |
| Registration #19 | 2013-10-02 | 79.142 mi |
| Registration #20 | 2013-10-02 | 79.142 mi |
| Registration #21 | 2013-10-02 | 79.142 mi |
| Registration #22 | 2013-10-02 | 79.142 mi |
| Registration #23 | 2013-10-02 | 79.142 mi |
| Registration #24 | 2013-10-02 | 79.142 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

| | |
|--------|---------|
| Width | 1750 mm |
| Height | 1435 mm |
| Length | 4810 mm |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 75 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Engine number | 00000000000829 |