






report date: 2024-03-28

#### General information

Make	BMW
Model	Z3 Z3 ROADSTER
Colour	Blue
Year of manufacture	2001
Top speed	122 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	117 BHP
Max. torque	180 Nm at 3.900 rpm
Engine capacity	1.895 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.8 mpg



CarCheck.co.uk page 1/14



## Internet history

#### Entry 1

Date 2021-11-08

Pictures 40

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-15
MOT pass rate	75 %
MOT passed	18
Failed MOT tests	6
Total advice items	33
Total items failed	8

MOT #24		2023-11-16 11:02
MOT test	number	971310435762
Result		✓ Passed
Next expi	ry date	2024-11-15
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Rear handbrake lower effort noted	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	<b>(</b> ))

MOT #23		2023-11-15 10:22
MOT test	number	838644607635
Result		🗙 Failed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> N	earside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (	<b>E))</b>
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Nearside Rear handbrake lower effort noted	

CarCheck.co.uk page 3/14



**MOT #22** 2022-11-15 10:10

**MOT test number** 868319040551

Result \rightarrow Passed

Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

**MOT #21** 2021-09-01 16:04

**MOT test number** 594283169131

**MOT #20** 2021-08-25 16:32

MOT test number 683490705565

Result X Failed

Fail Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Advice Underside of vehicle heavily covered in mud/dirt

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Brake hose slightly deteriorated both rear brake hoses perished (1.1.12 (b) (ii))

Advice Both sills have corrosion to front

Advice Brake pipe corroded, covered in grease or other material all brake pipes covered in dirt (1.1.11

(c))

MOT #19 2020-09-24 08:29

MOT test number 251454130638

Result 

Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

CarCheck.co.uk page 4/14



MOT #18		2019-09-23 08:28
MOT test	number	586453919068
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

Advice Offside Rear Tyre worn close to legal limit/worn on edg	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre worn close to legal limit/worn on e	dge (5.2.3 (e))	
MOT #17	2018-09-12 10:47	
MOT test number	128308787839	
Result	✓ Passed	
MOT #16	2017-09-18 13:48	
MOT test number	403228170373	
Result	<b>✓</b> Passed	
MOT #15	2016-09-20 12:58	
MOT test number	303243457450	
Result	✓ Passed	
MOT #14	2016-05-11 09:25	
MOT test number	195778750843	
Result	<b>√</b> Passed	
MOT #13	2016-05-11 09:17	
MOT test number	160201651002	
Result	<b>×</b> Failed	
Officido Poar position Jamp(s) not working (1.1 A.3h)		

Fail Offside Rear position lamp(s) not working (1.1.A.3b)

Fail Offside Rear Direction indicator incorrect colour (1.4.A.2f)

CarCheck.co.uk page 5/14



MOT #12

MOT test number

895126325106

Result

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Advice Offside Front Side repeater slightly discoloured (1.4.A.2f)

Notice Screw in osf tyre tread

Advice Nearside Front Side repeater slightly discoloured (1.4.A.2f)

MOT #11

MOT test number

Result

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT test number

Result

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

 MOT #9
 2013-05-10 11:58

 MOT test number
 645350833142

 Result
 ✓ Passed

CarCheck.co.uk page 6/14



MOT #8 2013-05-08 11:05

MOT test number 217918123143

**Result** X Failed

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Brakes imbalanced across an axle (3.7.B.5b)

MOT #7 2012-05-09 15:37

**MOT test number** 208620532420

**Result** ✓ Passed

MOT #6 2012-05-09 09:50

**MOT test number** 299870532142

**Result** X Failed

**Fail** Offside Inner Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #5 2011-05-10 15:15

**MOT test number** 759470831118

**Result** ✓ Passed

**MOT #4** 2009-09-04 15:37

MOT test number 362127449259

**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.5b)

**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 7/14



MOT #3	2008-09-08 12:35
MOT test number	952702558287
Result	<b>✓</b> Passed
Notice Front exhaust mount coroding	

Notice Front exhaust mount coroding	
NOT #2	2007 00 10 14 54
MOT #2	2007-09-18 14:54
MOT test number	453101167255
Result	✓ Passed
MOT #1	2006-04-05 17:36
MOT test number	961645596070
Result	✓ Passed

CarCheck.co.uk page 8/14



#### Tax & MOT check



Days left 279

MOT expiry date 15 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 9/14



#### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/14



$\alpha$	ner	hict	001
UVV	пег	msi	$\mathbf{o} \mathbf{v}$
		11100	<b>U</b> 1

, ,	
For how long did the current and previous owner(s) have this BMW? How many owners defined the current and see all owner registrations. Download the full report	
*********	
***************************************	
THE STATE OF THE S	
THE STATE OF THE S	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



## Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2001-01-12
Last registration	2023-11-16
Complete history	See info



Registration #1	2001-01-12	22 mi
Registration #2	2006-04-05	25.411 mi
Registration #3	2007-09-18	29.282 mi
Registration #4	2008-09-08	31.547 mi
Registration #5	2009-09-04	32.629 mi
Registration #6	2011-05-10	34.978 mi
Registration #7	2012-05-09	35.735 mi
Registration #8	2012-05-09	35.735 mi
Registration #9	2013-05-08	36.748 mi
Registration #10	2013-05-10	36.756 mi
Registration #11	2014-05-14	38.306 mi
Registration #12	2014-05-15	38.313 mi
Registration #13	2015-05-06	38.713 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.117 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		71,777 es

CarCheck.co.uk page 13/14



### Car features

50225	Air conditioning
50295	
50482	
60501	
60566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1740 mm
Height	1288 mm
Length	4025 mm
Wheel base	2446 mm
Kerb weight	1220 kg

# Additional information

Fuel tank capacity	51
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number CarCheck.co.uk	04779582 page 14/14