



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX20 STYLE
Colour	White
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-04
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-10
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	14
Total items failed	1

MOT #10	2023-05-12 11:50
MOT test number	944893333853
Result	✓ Passed
Next expiry date	2024-06-10

MOT #9	2022-05-26 14:17
MOT test number	916964423215
Result	✓ Passed

MOT #8	2022-05-26 09:06
MOT test number	391614107394
Result	✗ Failed
MAJOR Offside Headlamp levelling device inoperative (4.1.5 (a))	
MAJOR Central Rear Seat belt buckle missing stalk (7.1.2 (d))	
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	
MAJOR Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #7	2021-06-11 14:47
MOT test number	301789739924
Result	✓ Passed

**MOT #6** 2021-06-11 08:18**MOT test number** 687220710452**Result** ✗ Failed**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))**DANGEROUS** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #5** 2020-09-16 14:45**MOT test number** 995294303655**Result** ✓ Passed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #4** 2020-09-16 08:30**MOT test number** 757632808675**Result** ✗ Failed**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2019-09-07 09:34**MOT test number** 840834328941**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



MOT #2	2018-09-16 09:40
MOT test number	799024193860
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1	2017-08-29 11:50
MOT test number	183854502712
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
10 June 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	RK64VDG
Plate since	2024-03-29
Current registration	RK64VDG
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-09-13
Last registration	2023-05-12
Complete history	See info



Registration #1	2014-09-13	27 mi
Registration #2	2017-08-29	16.044 mi
Registration #3	2018-09-16	23.223 mi
Registration #4	2019-09-07	30.940 mi
Registration #5	2020-09-16	40.441 mi
Registration #6	2020-09-16	40.441 mi
Registration #7	2020-09-16	40.441 mi
Registration #8	2020-09-16	40.441 mi
Registration #9	2020-09-16	40.441 mi
Registration #10	2020-09-16	40.441 mi
Registration #11	2020-09-16	40.441 mi
Registration #12	2020-09-16	40.441 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	G4FAEZ578235
---------------	--------------