



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA 16V EXCLUSIVE
Colour	Grey
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2020-11-21 13:03
MOT test number	954503731935
Result	✓ Passed
Next expiry date	2021-11-30
Advice	Offside Front tyre pershing cracks

MOT #13	2020-11-21 13:03
MOT test number	914773107292
Result	✗ Failed
Advice	Offside Front tyre pershing cracks
Pass with rectification	Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))
Pass with rectification	Front Position lamp not working both sides (4.2.1 (a) (ii))

MOT #12	2019-06-01 11:03
MOT test number	751023288897
Result	✓ Passed
Advice	Direction indicator slightly discoloured both rear (4.4.3 (a))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2019-05-24 15:05
MOT test number	216397477286
Result	✗ Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Direction indicator slightly discoloured both rear (4.4.3 (a))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Nearside Front Suspension component ball joint dust cover no longer prevents the ingress of dirt bottom ball joint (5.3.4 (b) (ii))

**MOT #10** 2018-05-24 14:12**MOT test number** 869966865773**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside rear tyre tapering on the outer edge**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2017-05-09 13:55**MOT test number** 351273616550**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2017-05-09 11:42**MOT test number** 325326225567**Result** ✗ Failed**Fail** Rear Exhaust system not adequately supported (7.1.1)**Advice** Nearside Rear Outer Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2016-04-30 11:28**MOT test number** 886489902873**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2015-05-13 08:56**MOT test number** 276853335437**Result** ✓ Passed**MOT #5** 2014-05-17 10:34**MOT test number** 868327934141**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #4** 2014-05-17 09:07**MOT test number** 835057234193**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2013-05-22 11:33**MOT test number** 656802243181**Result** ✓ Passed**MOT #2** 2013-05-22 09:41**MOT test number** 249182543477**Result** ✗ Failed**Fail** Nearside Headlamp aim too high (1.8)**Fail** Nearside All position lamps not working (1.1.A.3b)**MOT #1** 2012-05-09 14:20**MOT test number** 766950732182**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-06-12
Last registration	2020-11-21
Complete history	See info



Registration #1	2009-06-12	29 mi
Registration #2	2012-05-09	21.890 mi
Registration #3	2013-05-22	30.981 mi
Registration #4	2013-05-22	30.981 mi
Registration #5	2014-05-17	40.456 mi
Registration #6	2014-05-17	40.456 mi
Registration #7	2015-05-13	49.437 mi
Registration #8	2016-04-30	58.365 mi
Registration #9	2016-05-20	58.365 mi
Registration #10	2016-05-20	58.365 mi
Registration #11	2016-05-20	58.365 mi
Registration #12	2016-05-20	58.365 mi
Registration #13	2016-05-20	58.365 mi
Registration #14	2016-05-20	58.365 mi
Registration #15	2016-05-20	58.365 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight

Width	1667 mm
Height	1612 mm
Length	3860 mm
Wheel base	2460 mm
Kerb weight	1133 kg
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX7S3417498