



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TOURAN SE TDI 105
Colour	Silver
Year of manufacture	-
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg





LABEL UNKNOWN



Internet history

Entry 2

Date	2021-11-07
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-09-26
Pictures	16
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history****MOT #14** 2022-12-10 15:53**MOT test number** 833235045722**Result** ✓ Passed**Next expiry date** 2023-12-09**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Suspension component corroded but not seriously weakened front and rear (5.3.3 (b) (i))**Advice** Rear Suspension component pin or bush slightly worn both (5.3.4 (a) (i))**MOT #13** 2021-08-04 15:03**MOT test number** 522731262152**Result** ✓ Passed**Advice** Electronic stability control warning lamp not working (7.12 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge (5.2.3 (e))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Suspension component pin or bush slightly worn both sides (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bold on edge (5.2.3 (e))

**MOT #12**

2021-07-27 11:57

**MOT test number**

836156222568

**Result****✗ Failed**

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Inner Suspension arm ball joint has slight play advise change with ball joint boot cover. (5.3.4 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm cords (5.2.3 (e))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Rear Suspension component pin or bush slightly worn both sides (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge bald on edge (5.2.3 (e))
- Fail** Nearside Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bold on edge (5.2.3 (e))
- Advice** Electronic stability control warning lamp not working (7.12 (e))

**MOT #11**

2020-07-29 09:17

**MOT test number**

193073017542

**Result****✓ Passed****MOT #10**

2020-07-29 09:17

**MOT test number**

277377088829

**Result****✗ Failed**

- Pass with rectification** Electronic stability control warning lamp indicates a fault (7.12 (e))

**MOT #9**

2019-07-17 15:33

**MOT test number**

148177115551

**Result****✓ Passed**

**MOT #8** 2018-07-26 11:34**MOT test number** 138926815913**Result** ✓ Passed**Minor** Suspension arm ball joint dust cover severely deteriorated Both front (5.3.4 (b) (i))**MOT #7** 2017-07-12 09:55**MOT test number** 140807742067**Result** ✓ Passed**MOT #6** 2016-07-20 14:16**MOT test number** 218837529289**Result** ✓ Passed**MOT #5** 2015-07-22 11:18**MOT test number** 567073505279**Result** ✓ Passed**Notice** Nearside front tyre worn on inner edge**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** 225/45R17W**MOT #4** 2014-07-21 12:40**MOT test number** 689512004232**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-08-07 17:13**MOT test number** 355839413478**Result** ✓ Passed



MOT #2	2012-09-28 16:59
MOT test number	459922172294
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2011-09-29 13:36
MOT test number	287832771236
Result	✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GY58MZZ</b>
Plate since	2024-03-29
Current registration	 <b>GY58MZZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-10-17
Last registration	2022-12-10
Complete history	<a href="#">See info</a>



Registration #1	2008-10-17	29 mi
Registration #2	2011-09-29	27.782 mi
Registration #3	2012-09-28	36.480 mi
Registration #4	2013-08-07	42.464 mi
Registration #5	2014-07-21	47.272 mi
Registration #6	2015-07-22	57.471 mi
Registration #7	2016-07-20	67.663 mi
Registration #8	2017-07-12	75.806 mi
Registration #9	2018-07-26	83.526 mi
Registration #10	2019-07-26	91.246 mi
Registration #11	2020-07-26	98.966 mi
Registration #12	2021-07-26	106.686 mi
Registration #13	2022-07-26	114.406 mi
Registration #14	2023-07-26	122.126 mi
Registration #15	2024-07-26	129.846 mi
Registration #16	2025-07-26	137.566 mi
Registration #17	2026-07-26	145.286 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1539 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE 719016