





report date: 2024-03-28

#### General information

Make	MINI
Model	COUNTRYMAN COOPER S E ALL4
Colour	Grey
Year of manufacture	2017
Top speed	123 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	221 BHP
Max. torque	385 Nm at 1.350 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Hybrid / Electric
Consumption combined	134.5 mpg
CO2 emission	49 g/km
CO2 label	A



CarCheck.co.uk page 1/11



NA67AOX report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-11

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2025-03-31
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	17
Total items failed	0

MOT #7	2024-03-18 17:09
MOT test number	404736228817
Result	✓ Passed
Next expiry date	2025-03-31
Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #6		2024-03-18 15:33
MOT test number	r	808574968230
Result		<b>X</b> Failed
<b>Advice</b> Nears	ide Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
DANGEROUS	Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>Advice</b> Nears	ide Front Wheel bearing has slight play (5.1.3 (a) (i))	
<b>DANGEROUS</b> 225/55R17 (5.2.3	Nearside Front Tyre has a bulge, caused by separation or partial failu(d) (ii))	ire of its structure

MOT #5	2023-03-16 14:46
MOT test number	864589877907
Result	<b>✓</b> Passed
Advice Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT test number

Result

MAJOR

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge 225/5517 (5.2.3 (e))

Advice

Child Seat fitted not allowing full inspection of adult belt

MOT #3

MOT test number

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2

MOT test number

443429016614

Result

√ Passed

**MOT #1** 2020-12-03 12:26 389435951410 **MOT** test number Result **X** Failed **Advice** Sharp edges front bumper **MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Difficult to open bonnet Offside Front Headlamp aim too high (4.1.2 (a)) MAJOR Advice Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **MAJOR** 

CarCheck.co.uk page 4/11



report date: 2024-03-28

#### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	31 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	59
Band	В
First licence fee (12 months)	£ 0,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
********	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	AIR NE
Plate since	
Current registration	NE NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



NA67AOX report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 9/11



NA67AOX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-12-18
Last registration	2024-03-18
Complete history	See info



Registration #1	2017-12-18	10 mi
Registration #2	2020-12-03	58.402 mi
Registration #3	2021-03-23	58.466 mi
Registration #4		11.777 es
Registration #5	2022-04-01	64.448 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	90%
Children	80%
Pedestrian	64%
Safety systems	51%
Overall rating	75%
Video	see crash video



## Dimensions & weight

Width	1822 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1735 kg
Max. allowed weight	2270 kg

## Additional information

Fuel tank capacity	36 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles 2

**Engine number** F288H583