



report date: 2024-03-29

General information

Make	MAZDA
Model	3 TS
Colour	Red
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-12-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-05
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	22
Total items failed	3

MOT #16 2023-07-14 09:23

MOT test number 521969944814

Result ✓ Passed

Next expiry date 2024-07-25

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #15 2023-07-14 09:23

MOT test number 143148847820

Result ✗ Failed**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #14 2022-07-20 12:26

MOT test number 762121116207

Result ✓ Passed

**MOT #13**

2021-07-26 12:42

MOT test number

223886010763

Result

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases silencer leaking (6.1.2 (a))
- Advice** Underside has general corrosion including suspension, nothing considered excessive or seriously weakened at present
- Advice** Exhaust system in poor condition
- Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))
- Advice** Rear bumper lower mount broken

MOT #12

2021-05-08 09:19

MOT test number

204958276591

Result

✓ Passed

- Advice** Slight exhaust leak
- Advice** Nearside Front anti roll bar link gaiter has slight damage
- Advice** Surface corrosion on underside and parts of suspension
- Advice** Rear bumper lower mounts broken off
- Advice** Offside Rear tyre has a nail on inner edge of tread

MOT #11

2020-10-23 11:42

MOT test number

192333162767

Result

✓ Passed

- Advice** All underside showing signs off corrosion

**MOT #10** 2019-10-25 14:14**MOT test number** 146652013651**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** All underside slightly corroded**Advice** Offside Front Play in steering rack inner joint(s)**MOT #9** 2018-10-26 12:51**MOT test number** 830169073706**Result** ✓ Passed**MOT #8** 2018-10-25 11:31**MOT test number** 995269030371**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #7** 2017-10-25 15:29**MOT test number** 706749841558**Result** ✓ Passed**MOT #6** 2017-10-25 10:31**MOT test number** 264865927979**Result** ✗ Failed**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2016-10-24 09:19**MOT test number** 351553692513**Result** ✓ Passed



MOT #4	2015-10-26 17:22
MOT test number	139448098536
Result	✓ Passed
MOT #3	2015-03-30 09:34
MOT test number	198729385433
Result	✓ Passed
MOT #2	2014-03-27 15:56
MOT test number	108866484483
Result	✓ Passed
MOT #1	2013-03-25 09:57
MOT test number	947924583023
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
9 September 2023

✓

MOT

Expires:
25 July 2024

Tax status	Expired at 9 September
Days left	234 days too late
MOT expiry date	25 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-03-31
Last registration	2023-07-14
Complete history	See info



Registration #1	2010-03-31	9 mi
Registration #2	2013-03-25	26.512 mi
Registration #3	2014-03-27	30.461 mi
Registration #4	2015-03-30	36.731 mi
Registration #5	2015-10-26	41.067 mi
Registration #6	2016-10-24	49.609 mi
Registration #7	2017-10-25	57.662 mi
Registration #8	2017-10-25	57.666 mi
Registration #9	2018-10-25	63.740 mi
Registration #10	2018-10-26	63.743 mi
Registration #11	2019-10-26	69.787 mi
Registration #12	2019-10-26	69.791 mi
Registration #13	2019-10-26	69.795 mi
Registration #14	2019-10-26	69.799 mi
Registration #15	2019-10-26	69.803 mi
Registration #16	2019-10-26	69.807 mi
Registration #17	2019-10-26	69.811 mi
Registration #18	2019-10-26	69.815 mi
Registration #19	2019-10-26	69.819 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4580 mm
Wheel base	2640 mm
Kerb weight	1235 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	Z6 862414