



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Beige
Year of manufacture	-
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-06
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #17	2020-10-06 14:34
MOT test number	468597265855
Result	✓ Passed
Next expiry date	2021-10-05
Advice	Headlamp has a product on the lens but not seriously reducing light output Both. (4.1.4 (b))

MOT #16	2019-09-04 14:21
MOT test number	186954932324
Result	✓ Passed
Advice	Offside Rear Nail in tyre

MOT #15	2018-09-25 09:12
MOT test number	830141824429
Result	✓ Passed
Advice	Headlamp has a product on the lens but not seriously reducing light output Both lenses misted. (4.1.4 (b))

MOT #14	2017-08-08 13:11
MOT test number	608560087448
Result	✓ Passed

MOT #13	2016-08-18 11:54
MOT test number	727297925037
Result	✓ Passed

MOT #12	2015-08-07 11:45
MOT test number	357349115479
Result	✓ Passed

Advice Nearside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement
(2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement
(2.4.G.2)

**MOT #11**

2015-08-07 09:24

MOT test number

437239815259

Result

✗ Failed

Fail Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear Trailing arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #10**

2014-08-20 09:43

MOT test number

877252334258

Result

✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9**

2013-08-29 09:48

MOT test number

329701943431

Result

✓ Passed

Notice Headlamp masks/converters fitted**MOT #8**

2012-08-16 10:39

MOT test number

446129822219

Result

✓ Passed

Notice Rear seats removed-unable to fully check rear adult seat belts.

**MOT #7** 2012-05-14 11:54**MOT test number** 176925332136**Result** ✓ Passed**Notice** Headlamp masks/converters fitted**Notice** Rear passenger seats not fitted at time of test-unable to fully check rear adult seat belts.**MOT #6** 2012-05-14 11:54**MOT test number** 207395232148**Result** ✗ Failed**Notice** Rear passenger seats not fitted at time of test-unable to fully check rear adult seat belts.**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Notice** Headlamp masks/converters fitted**MOT #5** 2011-08-19 10:50**MOT test number** 917391231242**Result** ✓ Passed**MOT #4** 2011-08-19 10:50**MOT test number** 315251631409**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2010-09-02 12:37**MOT test number** 251035340201**Result** ✓ Passed



MOT #2	2009-11-25 09:30
MOT test number	224529029368
Result	✓ Passed

MOT #1	2008-12-09 13:32
MOT test number	281624248306
Result	✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	LC55CVA
Plate since	2024-03-29
Current registration	LC55CVA
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2005-12-20
Last registration	2020-10-06
Complete history	See info



Registration #1	2005-12-20	12 mi
Registration #2	2008-12-09	77.155 mi
Registration #3	2009-11-25	105.231 mi
Registration #4	2010-09-02	109.632 mi
Registration #5	2011-08-19	115.630 mi
Registration #6	2012-05-14	119.899 mi
Registration #7	2012-08-16	120.489 mi
Registration #8	2013-08-29	125.120 mi
Registration #9	2014-08-20	132.766 mi
Registration #10	2015-05-20	135.377 mi
Registration #11	2016-05-20	135.377 mi
Registration #12	2017-05-20	135.377 mi
Registration #13	2018-05-20	135.377 mi
Registration #14	2019-05-20	135.377 mi
Registration #15	2020-05-20	135.377 mi
Registration #16	2021-05-20	135.377 mi
Registration #17	2022-05-20	135.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1CD0491619