



HONDA




report date: 2024-03-28

General information

Make	HONDA
Model	HR-V 4WD
Colour	Blue
Year of manufacture	2002
Top speed	101 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Max. torque	135 Nm at 3.400 rpm
Engine capacity	1.590 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	37.7 mpg
Consumption combined	33.6 mpg
CO2 emission	204 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-01-31
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date 2022-02-09**MOT pass rate** 67 %**MOT passed** 16**Failed MOT tests** 8**Total advice items** 28**Total items failed** 24**MOT #24** 2022-02-08 15:48**MOT test number** 129946400005**Result** ✗ Failed**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on inner shoulder (5.2.3 (e))**Advice** Anti-roll bar linkage ball joint has slight play osr nsf osf (5.3.4 (a) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement nsr osr D bushes (5.3.4 (a) (i))**Fail** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))**MOT #23** 2021-02-10 08:13**MOT test number** 268572362702**Result** ✓ Passed

**MOT #22** 2021-02-09 14:31**MOT test number** 581662892153**Result** ✗ Failed

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))
- Fail** Central Rear Brake pipe excessively corroded 2 pipes (1.1.11 (c))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #21 2020-01-21 16:41**MOT test number** 872640926565**Result** ✓ Passed**MOT #20** 2020-01-21 16:41**MOT test number** 662995284854**Result** ✗ Failed

- Pass with rectification** Offside Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #19 2019-01-02 15:07**MOT test number** 465855294873**Result** ✓ Passed**MOT #18** 2017-12-19 16:59**MOT test number** 367695668691**Result** ✓ Passed



MOT #17	2016-12-09 12:34
MOT test number	663290596776
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #16	2016-12-08 14:38
MOT test number	740337777834
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Stop lamp not working (1.2.1b)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #15	2016-11-12 11:23
MOT test number	590124973806
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit On 2mm (4.1.E.1)
Fail	Exhaust has a major leak of exhaust gases Middle section to back box (7.1.2)
Advice	Both front wipers slightly smearing - Not to excess
Fail	Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)
Advice	Nearside Front Tyre worn close to the legal limit On 1.6mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit On 2mm (4.1.E.1)
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)
Fail	Nearside Stop lamp not working (1.2.1b)

**MOT #14** 2015-11-07 12:10**MOT test number** 856609976358**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2015-11-07 12:10**MOT test number** 805461120746**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2014-11-15 10:09**MOT test number** 755329014329**Result** ✓ Passed**MOT #11** 2013-12-04 17:01**MOT test number** 535408033308**Result** ✓ Passed**Notice** Front pads close to limit**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Notice** N/S/R tyre starting to wear on inner edge**Notice** O/S/F tyre has a cut but not showing cords**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Notice** N/S/F tyre starting to wear on outer edge

**MOT #10** 2013-12-03 14:28**MOT test number** 405917333494**Result** ✗ Failed**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** Front pads close to limit**Advice** Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**Notice** N/S/R tyre starting to wear on inner edge**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** O/S/F tyre has a cut but not showing cords**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Notice** N/S/F tyre starting to wear on outer edge**Advice** Offside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)**MOT #9** 2012-11-10 11:25**MOT test number** 646655112376**Result** ✓ Passed**Notice** Advise n/s front seat belt slightly frayed**Notice** Advise o/s front drop link slight play**MOT #8** 2012-11-05 09:59**MOT test number** 519160512358**Result** ✗ Failed**Notice** Advise n/s front seat belt slight fraying**Fail** Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)**Notice** Advise o/s front drop link slight play



MOT #7	2011-11-19 10:11
---------------	------------------

MOT test number	569023521320
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2010-11-13 08:24
---------------	------------------

MOT test number	284067410341
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2009-11-05 18:33
---------------	------------------

MOT test number	173989609325
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2008-11-04 10:52
---------------	------------------

MOT test number	271559608319
------------------------	--------------

Result	✓ Passed
---------------	----------

Notice	Child seat fitted not allowing full inspection of adult belt
---------------	--

MOT #3	2007-10-01 12:17
---------------	------------------

MOT test number	384594177262
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2006-11-01 13:50
---------------	------------------

MOT test number	421025706425
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2005-06-29 12:19
---------------	------------------

MOT test number	791360785156
------------------------	--------------

Result	✓ Passed
---------------	----------



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-06-27
Last registration	2022-02-08
Complete history	See info



Registration #1	2002-06-27	18 mi
Registration #2	2005-06-29	28.856 mi
Registration #3	2006-11-01	36.542 mi
Registration #4	2007-10-01	40.029 mi
Registration #5	2008-11-04	43.181 mi
Registration #6	2009-11-05	47.067 mi
Registration #7	2010-11-13	55.638 mi
Registration #8	2011-11-19	63.863 mi
Registration #9	2012-11-05	72.528 mi
Registration #10	2012-11-10	72.529 mi
Registration #11	2013-12-03	82.713 mi
Registration #12	2013-12-04	82.713 mi
Registration #13	2014-11-15	91.428 mi
Registration #14	2015-05-20	95.337 mi
Registration #15	2015-05-20	95.337 mi
Registration #16	2015-05-20	95.337 mi
Registration #17	2015-05-20	95.337 mi
Registration #18	2015-05-20	95.337 mi
Registration #19	2015-05-20	95.337 mi
Registration #20	2015-05-20	95.337 mi
Registration #21	2015-05-20	95.337 mi
Registration #22	2015-05-20	95.337 mi
Registration #23	2015-05-20	95.337 mi
Registration #24	2015-05-20	95.337 mi
Registration #25	2015-05-20	95.337 mi
Registration #26	2015-05-20	95.337 mi

More info >



Dimensions & weight

Width	2000 mm
Height	1700 mm
Length	4110 mm
Kerb weight	1125 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D16W11309786