




report date: 2024-03-29

General information

Make	SMART
Model	FORTWO COUPE PASSION 71
Colour	White
Year of manufacture	2008
Top speed	90 mph
0 - 100 km/h	13.3 seconds
0 - 60 mph	13.3 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	52 kW / 71 HP / 71 BHP
Max. torque	92 Nm at 4.500 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	112 g/km
CO2 label	C





MOT history

MOT expiry date	2025-01-30
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	27
Total items failed	17

MOT #22	2024-01-05 16:01
---------	------------------

MOT test number	534351862966
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-01-30
------------------	------------

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #21**

2024-01-05 15:37

MOT test number

170054159594

Result**✗ Failed****Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #20**

2023-01-31 08:47

MOT test number

398122839818

Result**✓ Passed****MOT #19**

2022-03-24 16:18

MOT test number

935083198424

Result**✓ Passed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #18** 2022-03-24 15:46**MOT test number** 385783526078**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Side repeater incorrect colour (4.4.3 (a))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #17** 2021-03-24 11:03**MOT test number** 499985912024**Result** ✓ Passed**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**MOT #16** 2021-03-24 11:03**MOT test number** 467916420388**Result** ✗ Failed**Pass with rectification** Central Rear Engine mounting damaged or deteriorated resulting in excessive movement (6.1.8 (a) (i))**Advice** Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement top mount (5.3.4 (a) (i))**MOT #15** 2020-01-23 12:57**MOT test number** 640768337372**Result** ✓ Passed**Advice** One rear exhaust support mount bracket broken**MOT #14** 2019-02-04 12:39**MOT test number** 231367013725**Result** ✓ Passed

**MOT #13** 2018-03-02 14:49**MOT test number** 398139206254**Result** ✓ Passed**MOT #12** 2018-02-24 14:20**MOT test number** 508626702112**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick both front (3.5.1g)**Fail** Offside Front Front suspension has excessive movement at a wishbone pin or bush inner bushes (2.5.A.1c)**Fail** Front Windscreen wiper does not clear the windscreen effectively both front (8.2.2)**MOT #11** 2017-02-27 15:50**MOT test number** 774545709626**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside rear tyre outer wall slightly deteriorated**MOT #10** 2016-01-27 13:27**MOT test number** 764306024138**Result** ✓ Passed**Advice** O/s/r tyre cracking on outer tread

**MOT #9** 2016-01-27 09:44**MOT test number** 317331469205**Result** ✗ Failed**Fail** Offside Rear Stop lamp not working (1.2.1b)**Advice** O/s/r tyre cracking on outer tread**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Fuel cap/sealing device sealing washer torn (7.2.4c)**MOT #8** 2015-02-16 17:02**MOT test number** 687357145042**Result** ✓ Passed**Advice** Exhaust noisy (7.1.4)**Notice** Light indicate fault on dash**MOT #7** 2015-02-16 10:13**MOT test number** 105287345461**Result** ✗ Failed**Fail** Exhaust system not adequately supported (7.1.1)**Fail** All position lamps adversely affected by the operation of another lamp (1.1.A.3f)**Advice** Exhaust noisy (7.1.4)**Notice** Light indicate fault on dash**Fail** Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Fail** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)

**MOT #6** 2014-02-24 16:43**MOT test number** 589765954086**Result** ✓ Passed**Notice** ADVICE both side front tyre has slight cracks on tread**Notice** Nail in offside rear tyre**MOT #5** 2013-02-25 11:26**MOT test number** 369546153022**Result** ✓ Passed**MOT #4** 2012-02-27 10:04**MOT test number** 477888652003**Result** ✓ Passed**MOT #3** 2012-02-27 10:04**MOT test number** 758168052015**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #2** 2011-02-28 14:53**MOT test number** 778959551048**Result** ✓ Passed**MOT #1** 2011-01-11 17:02**MOT test number** 257461011023**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 March 2025

✓
MOT

Expires:
30 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history


Check the damage history for this SMART. See if, where and when this SMART had damage and the car repair costs. We also check if this SMART was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SMART salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SMART in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SMART? How many owners did this SMART have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this SMART had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this SMART is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SMART has been settled.

If not, and you buy this SMART then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SMART is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-01-31
Last registration	2024-01-05
Complete history	See info



Registration #1	2008-01-31	17 mi
Registration #2	2011-01-11	22.125 mi
Registration #3	2011-02-28	22.136 mi
Registration #4	2012-02-27	25.865 mi
Registration #5	2013-02-25	30.022 mi
Registration #6	2014-02-24	34.325 mi
Registration #7	2015-02-16	38.284 mi
Registration #8	2015-02-16	38.284 mi
Registration #9	2016-01-27	43.143 mi
Registration #10	2016-01-27	43.143 mi
Registration #11	2017-02-27	45.993 mi
Registration #12	2018-02-27	48.843 mi
Registration #13	2019-02-27	51.693 mi
Registration #14	2020-02-27	54.543 mi
Registration #15	2021-02-27	57.393 mi
Registration #16	2022-02-27	60.243 mi
Registration #17	2023-02-27	63.093 mi
Registration #18	2024-01-05	65.943 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1559 mm
Height	1542 mm
Length	2695 mm
Wheel base	1867 mm
Kerb weight	725 kg
Max. allowed weight	1020 kg

Additional information

Fuel tank capacity	33 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	3B21BD4139