



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 XC70 D5 SE SPORT
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	185 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.2 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-02-06
Pictures	44
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-25
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	48
Total items failed	70

MOT #21 2023-09-26 12:40

MOT test number 965027070211

Result ✓ Passed

Next expiry date 2024-09-25

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))
- Advice** Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement Trailing arm (5.3.4 (a) (i))

MOT #20 2022-09-15 13:34

MOT test number 977823373173

Result ✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #19**

2022-09-02 10:41

MOT test number

349330302863

Result**✗ Failed**

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Advice Oil leak, but not excessive engine (8.4.1 (a) (i))

Fail Offside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn front bush (5.3.4 (a) (i))

MOT #18

2021-08-13 16:04

MOT test number

959171625061

Result**✓ Passed**

Advice Coil spring corroded all round (5.3.1 (b) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #17**

2021-08-13 12:12

MOT test number

351323812921

Result**✗ Failed**

- Fail** Rear Exhaust silencer insecure (8.1.1 (b) (i))
- Fail** Front Headlamp not working on dipped beam both (4.1.1 (a) (ii))
- Fail** Front Inner Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coil spring corroded all round (5.3.1 (b) (i))

MOT #16

2020-08-12 12:59

MOT test number

922054546531

Result**✓ Passed****MOT #15**

2020-07-31 12:19

MOT test number

109030310757

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))

MOT #14

2020-01-21 16:19

MOT test number

435990089863

Result**✓ Passed**

- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #13**

2020-01-09 14:49

MOT test number

288231836403

Result**✗ Failed**

- Fail** Nearside Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface light unit (4.8.1 (a) (ii))
- Fail** Nearside Front Suspension arm pin or bush excessively worn front bush on arm (5.3.4 (a) (i))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Headlamp aim too low (4.1.2 (a))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #12

2019-02-16 10:11

MOT test number

414526598556

Result**✓ Passed**

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2019-02-08 14:53

MOT test number

399518698842

Result**✗ Failed**

- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Nearside Rear Service brake effort inadequate at a wheel (1.2.1 (a) (i))
- Fail** Nearside Rear Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Power steering inoperative steering tight (2.1.5 (c) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Steering rack has excessive free play detected at the steering wheel (steering rack fitted) steering arm (2.3 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn front bush on arm (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Rear Service brake has no recorded effort at a wheel (1.2.1 (a) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))



MOT #10	2018-01-29 15:37
MOT test number	201927286999
Result	✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #9**

2018-01-25 16:42

MOT test number

185375435656

Result**✗ Failed**

Fail Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Rear Brakes imbalanced across an axle (3.7.B.5b)

Fail Offside Headlamp not working on dipped beam (1.7.5a)

Fail Parking brake: efficiency below requirements (3.7.B.7)

Fail Offside rear parking brake recording little or no effort (3.7.B.6a)

Fail Offside Front wheel bearing has excessive play (2.5.A.3c)

Fail Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint drop link (2.4.G.2)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Front Brakes imbalanced across an axle (3.7.B.5b)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

Fail Nearside rear parking brake recording little or no effort (3.7.B.6a)

Fail Rear registration plate deteriorated (6.3.1d)

Fail Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)

Fail Nearside rear brake binding (3.7.B.1)



MOT #8	2017-01-11 12:15
MOT test number	630922813985
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2017-01-06 14:34
MOT test number	417572145415
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear rear parking brake recording little or no effort (3.7.B.6a)
Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6**

2017-01-06 12:26

MOT test number

882057447610

Result**✗ Failed****Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Advice rear number plate**Fail** Nearside Front Headlamp aim too low (1.8)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Parking brake: efficiency below requirements (3.7.C.1b)**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Advice on further look at foot brake**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #5**

2014-06-06 12:39

MOT test number

437567854106

Result**✓ Passed****Notice** Advice on slight hand brake travel and further look at hand brake**Notice** Advice on o/s/f headlight**Advice** Rear Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)

**MOT #4** 2013-06-07 12:15**MOT test number** 359818253130**Result** ✓ Passed**Notice** Advice on rear brake discs and further look at rear brakes**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.C.1b)**Notice** Advice on slight hand brake travel and further look at hand brake**MOT #3** 2012-03-09 16:48**MOT test number** 827039762051**Result** ✓ Passed**Notice** Engine management light on**Notice** Small stonechip on windscreen**Notice** Monitor front brake pads for wear**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #2** 2011-03-05 11:03**MOT test number** 518904161054**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Track rod end ball joint has slight play (2.2.B.1f)**MOT #1** 2010-03-11 14:34**MOT test number** 493850470011**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 March 2024

✓

MOT

Expires:
25 September 2024

Tax status	Expired at 1 March 2024
Days left	58 days too late
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SM07KXO
Plate since	2019-09-28
Current registration	SM07KXO
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-03-30
Last registration	2023-09-26
Complete history	See info



Registration #1	2007-03-30	29 mi
Registration #2	2010-03-11	33.259 mi
Registration #3	2011-03-05	48.624 mi
Registration #4	2012-03-09	57.477 mi
Registration #5	2013-06-07	69.830 mi
Registration #6	2014-06-06	83.945 mi
Registration #7	2017-01-06	99.921 mi
Registration #8	2017-01-06	99.929 mi
Registration #9	2017-01-11	99.939 mi
Registration #10	2018-01-25	106.498 mi
Registration #11	2018-01-29	106.498 mi
Registration #12	2019-02-08	113.536 mi
Registration #13	2019-05-20	121.577 mi
Registration #14	2019-05-20	121.577 mi
Registration #15	2019-05-20	121.577 mi
Registration #16	2019-05-20	121.577 mi
Registration #17	2019-05-20	121.577 mi
Registration #18	2019-05-20	121.577 mi
Registration #19	2019-05-20	121.577 mi
Registration #20	2019-05-20	121.577 mi
Registration #21	2019-05-20	121.577 mi
Registration #22	2019-05-20	121.577 mi
Registration #23	2019-05-20	121.577 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1860 mm
Height	1562 mm
Length	4733 mm
Wheel base	2763 mm
Kerb weight	1719 kg
Max. allowed weight	2220 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	432080