



report date: 2024-03-28

General information

Make	KIA
Model	SEDONA TS
Colour	Black
Year of manufacture	2007
Top speed	122 mph
0 - 60 mph	15.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	182 BHP
Max. torque	343 Nm at 4.500 rpm
Engine capacity	2.902 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	206 g/km
CO2 label	K






Internet history

Entry 2


Date	2021-07-04
Pictures	30
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-07-03
Pictures	30
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	31
Total items failed	10

MOT #19	2024-01-31 11:48
MOT test number	254035724152
Result	✓ Passed
Next expiry date	2025-01-30

MOT #18	2023-01-05 13:31
MOT test number	101656773480
Result	✓ Passed

MOT #17	2021-10-28 12:36
MOT test number	838712726329
Result	✓ Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2020-08-25 14:55
MOT test number	305446284914
Result	✓ Passed

Advice REAR SUSPENSION COMPONENTS CORRODED

Advice Oil leak, but not excessive (8.4.1 (a) (i))



MOT #15	2020-08-20 15:46
MOT test number	433071839628
Result	✗ Failed
Fail	Offside Front Service brake excessively binding (1.2.1 (f))
Advice	Nearside Rear Nail in tyre OUTER EDGE
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	REAR SUSPENSION COMPONENTS CORRODED
Fail	Front Brakes imbalanced across an axle (1.2.1 (b) (i))
Fail	Offside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #14**

2019-08-21 10:31

MOT test number

796666930266

Result

✓ Passed

- Advice** Offside Front tyre has bald patches on inner shoulder
- Advice** Nearside Front tyre worn on shoulders
- Advice** Clutch pedal fault
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front and rear brake service recommended
- Advice** Mil lamp on
- Advice** Oil leak
- Advice** Rear coil springs corroded
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #13

2018-09-01 10:02

MOT test number

961659610269

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #12

2017-09-04 13:42

MOT test number

822413246156

Result

✓ Passed

- Advice** Offside Rear Outer tyre sidewall damaged
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Oil leak

**MOT #11** 2017-09-04 13:42**MOT test number** 365011305697**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Outer tyre sidewall damaged**Pass with rectification** Nearside Stop lamp not working (1.2.1b)**Advice** Oil leak**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2016-09-12 14:27**MOT test number** 534592912114**Result** ✓ Passed**MOT #9** 2016-09-12 14:27**MOT test number** 965240214285**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2015-09-05 12:30**MOT test number** 620664299239**Result** ✓ Passed**MOT #7** 2015-09-05 11:39**MOT test number** 756087854518**Result** ✗ Failed**Fail** Exhaust emits an excessive level of metered smoke for a turbo charged engine (7.4.B.3b)

**MOT #6** 2014-09-01 15:59**MOT test number** 377924344203**Result** ✓ Passed**MOT #5** 2013-08-28 08:51**MOT test number** 326830743497**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Oil leak**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2012-09-01 12:03**MOT test number** 648305942241**Result** ✓ Passed**Advice** Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #3** 2011-08-30 11:53**MOT test number** 689042641208**Result** ✓ Passed**Advice** Offside Front Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2010-08-24 11:27**MOT test number** 884276330267**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-08-24 10:24
MOT test number	371156430480
Result	✗ Failed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Stop lamp not working (1.2.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
30 January 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-09-08
Last registration	2024-01-31
Complete history	See info



Registration #1	2007-09-08	28 mi
Registration #2	2010-08-24	26.221 mi
Registration #3	2010-08-24	26.221 mi
Registration #4	2011-08-30	28.062 mi
Registration #5	2012-09-01	29.857 mi
Registration #6	2013-08-28	34.485 mi
Registration #7	2014-09-01	42.975 mi
Registration #8	2015-09-05	50.198 mi
Registration #9	2015-09-05	50.198 mi
Registration #10	2016-09-12	57.319 mi
Registration #11	2016-09-12	57.319 mi
Registration #12	2017-09-12	64.440 mi
Registration #13	2017-09-12	64.440 mi
Registration #14	2018-09-12	71.561 mi
Registration #15	2018-09-12	71.561 mi
Registration #16	2019-09-12	78.682 mi
Registration #17	2019-09-12	78.682 mi
Registration #18	2020-09-12	85.803 mi
Registration #19	2020-09-12	85.803 mi
Registration #20	2021-09-12	92.924 mi
Registration #21	2021-09-12	92.924 mi
Registration #22	2024-01-31	100.045 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video [see crash video](#)



Dimensions & weight

Width	1985 mm
Height	1815 mm
Length	4810 mm
Wheel base	2890 mm
Kerb weight	2168 kg
Max. allowed weight	2900 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	J3763880