

Ø



General information

Make	LEXUS
Model	IS 300H SPORT
Colour	Black
Year of manufacture	2019
Top speed	125 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	220 BHP	0 < 101 A
Max. torque	520 Nm at 4.200 rpm	101 - 120 B
Engine capacity	2.494 cc	121 - 140 E
Cylinders	4	141 - 165 F
Fuel type	Hybrid / Electric	166 - 185
Consumption combined	45.6 mpg	186 - 225 J
CO2 emission	109 g/km	225+ L
CO2 label	В	



Internet history

Entry 1

Date

Pictures

2021-10-14

2

Lexus Cardiff

Website Directions Save Call 4.8 ***** 100 Google reviews Lexus dealer in Cartill, Wales

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-24
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	1
Total items failed	4

МОТ #3	2023-10-25 09:12
MOT test number	512882035783
Result	✓ Passed
Next expiry date	2024-10-24
Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the (d) (i))	ply or cords Sidewall (5.2.3

MOT #2	2022-12-02 16:08
MOT test number	352433790024
Result	✓ Passed

MOT #1	2022-12-02 10:08
MOT test number	376378526834
Result	🗙 Failed
Fail Offside Front Tyre has a cut in excess of the requirements deep enough to (5.2.3 (d) (i))	reach the ply or cords
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Nearside Windscreen washer not working (3.5 (a))	
FailOffside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 24 October 2024
Tax status	Valid until 1 November
Days left	186
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	F
First licence fee (12 months)	£ 175,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	Anne
Туре	K K
Damage 2	AMPLE
Damage 2	e et - I - I
Date	S.
Category	AMPT
Туре	

Extra LEXUS salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this LEXUS had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LEXUS is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



RV69VMP report date: 2024-03-28

Mileage check

Odometer	In miles	ſ
Mileage registrations	5	mileade
First mileage registration	2019-11-19	Ē
Last registration	2023-10-25	
Complete history	See info	



Registration #1	2019-11-19	23 mi
Registration #2		11.777 est
Registration #3	2022-12-02	32.955 mi
Registration #4		11.777 est
Registration #5		11.117 mi



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
\$0567	
S0569	

Safety ratings

NCAP rating	****
Adult	91%
Children	85%
Pedestrian	80%
Safety systems	66%
Overall rating	85%
Video	see crash video



Dimensions & weight	
Width	1810 mm
Height	1430 mm
Length	4680 mm
Max. allowed weight	2145 kg
Additional information	
Number of seats	5
Number of axles	2

2AR2066153

Engine number