



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	White
Year of manufacture	2011
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	72.4 mpg
Consumption combined	61.4 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-04-06
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

Entry 1

Date	2021-07-18
Pictures	2
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-31
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	9

MOT #13	2023-05-30 13:18
MOT test number	465594705775
Result	✓ Passed
Next expiry date	2024-05-31
Minor	Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))
Advice	Oil leak, but not excessive Gearbox (8.4.1 (a) (i))

MOT #12	2022-06-01 17:13
MOT test number	631159766291
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Nearside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #11	2020-10-26 10:54
MOT test number	332234996368
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2020-10-23 13:35

**MOT test number**

739364911771

**Result****✗ Failed**

- Fail** Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Offside Front Upper Macpherson strut top bush or bearing has excessive wear or free play (5.3.4 (a) (i))
- Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Fail** Offside Rear Upper Shock absorbers has an excessively worn bush (5.3.2 (c))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #9**

2019-11-01 16:06

**MOT test number**

653703527800

**Result****✓ Passed**

- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view zone b (3.2 (a) (i))

**MOT #8**

2019-10-30 12:58

**MOT test number**

494435871184

**Result****✗ Failed**

- Fail** Offside Rear Inner Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Rear Wheel bearing slightly noisy (5.1.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view zone b (3.2 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))

**MOT #7** 2018-10-23 08:17**MOT test number** 544495202470**Result** ✓ Passed**Minor** Nearside Upper Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #6** 2017-10-24 11:51**MOT test number** 413639815714**Result** ✓ Passed**Advice** Nearside Front tyre worn on inner edge**MOT #5** 2016-11-01 09:23**MOT test number** 822921590725**Result** ✓ Passed**MOT #4** 2016-03-24 11:31**MOT test number** 215789699145**Result** ✓ Passed**MOT #3** 2015-03-31 16:35**MOT test number** 165120595026**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2014-04-04 15:09**MOT test number** 127994294449**Result** ✓ Passed



MOT #1	2014-04-03 14:45
MOT test number	297303694050
Result	✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Obligatory mirror insecure (8.1.1)
Fail	Offside Stop lamp not working (1.2.1b)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
31 May 2024

<b>Tax status</b>	Valid until 1 March
-------------------	---------------------

<b>Days left</b>	306
------------------	-----

<b>MOT expiry date</b>	31 May 2024
------------------------	-------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-31
Last registration	2023-05-30
Complete history	<a href="#">See info</a>



Registration #1	2011-03-31	27 mi
Registration #2	2014-04-03	38.625 mi
Registration #3	2014-04-04	38.625 mi
Registration #4	2015-03-31	43.020 mi
Registration #5	2016-03-24	46.714 mi
Registration #6	2016-11-01	48.350 mi
Registration #7	2017-10-24	57.882 mi
Registration #8	2018-10-23	69.198 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1321 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982964254