



SMI3BBZ

report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	White
Year of manufacture	2013
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	43.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	56.5 mpg
CO2 emission	133 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-29
Pictures	11
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-12-19
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	9
Total items failed	14

MOT #15	2023-12-20 12:33
MOT test number	153601917759
Result	✓ Passed
Next expiry date	2024-12-19

MOT #14	2023-12-18 18:36
MOT test number	847172039913
Result	✗ Failed
Fail	Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
Advice	Both side front shock mounts

MOT #13	2022-10-19 10:46
MOT test number	707221387469
Result	✓ Passed

MOT #12	2021-07-01 10:46
MOT test number	147305225548
Result	✓ Passed

MOT #11	2021-03-09 12:53
MOT test number	850642135293
Result	✓ Passed

**MOT #10** 2020-02-03 11:52**MOT test number** 418988985068**Result** ✓ Passed**MOT #9** 2020-02-01 10:14**MOT test number** 137202211687**Result** ✗ Failed**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #8** 2019-02-14 16:06**MOT test number** 572222313438**Result** ✓ Passed**MOT #7** 2019-02-12 14:59**MOT test number** 123493263430**Result** ✗ Failed**Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2018-05-25 12:37**MOT test number** 667700875141**Result** ✓ Passed**Advice** Front brakedisc s corroded

**MOT #5** 2018-05-14 13:31**MOT test number** 220663284287**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Shock absorber has an excessively worn shock absorber pivot Top bearing (2.7.4)**Advice** Front brakedisc s corroded**MOT #4** 2017-06-05 10:13**MOT test number** 391117674476**Result** ✓ Passed**MOT #3** 2017-06-05 08:10**MOT test number** 953845809485**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #2** 2016-06-11 11:54**MOT test number** 532312280538**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #12016-06-10 16:18

MOT test number500230789020

Result		✗ Failed
Fail	Nearside Stop lamp not working (1.2.1b)	
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
19 December 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



report date: 2024-03-28

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-06-18
Last registration	2023-12-20
Complete history	See info



Registration #1	2013-06-18	25 mi
Registration #2	2016-06-10	50.040 mi
Registration #3	2016-06-11	50.040 mi
Registration #4	2017-06-05	64.938 mi
Registration #5	2017-06-05	64.938 mi
Registration #6	2018-05-14	74.061 mi
Registration #7	2018-05-25	74.061 mi
Registration #8	2019-02-12	77.480 mi
Registration #9	2019-02-14	77.500 mi
Registration #10	2019-06-20	80.277 mi
Registration #11	2019-06-20	80.277 mi
Registration #12	2019-06-20	80.277 mi
Registration #13	2019-06-20	80.277 mi
Registration #14	2019-06-20	80.277 mi
Registration #15	2019-06-20	80.277 mi
Registration #16	2019-06-20	80.277 mi
Registration #17	2019-06-20	80.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	4945767