



AK09BHW

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT TDI S
Colour	Grey
Year of manufacture	-
Top speed	117 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	250 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	48.7 mpg



**MOT history****MOT #15** 2022-02-26 16:10**MOT test number** 319624339639**Result** ✓ Passed**Next expiry date** 2023-02-26

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14** 2021-02-14 15:23**MOT test number** 558961508887**Result** ✓ Passed

- Advice** Rear Shock absorbers light misting of oil or has limited damping effect Both rear (5.3.2 (b))
- Advice** Tyre worn close to legal limit/worn on edge All 4 tyres (5.2.3 (e))

**MOT #13** 2021-02-14 15:22**MOT test number** 736498099816**Result** ✗ Failed

- Advice** Tyre worn close to legal limit/worn on edge All 4 tyres (5.2.3 (e))
- Advice** Rear Shock absorbers light misting of oil or has limited damping effect Both rear (5.3.2 (b))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**MOT #12** 2020-02-24 14:08**MOT test number** 840038961603**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #11** 2020-02-22 12:02**MOT test number** 974161842590**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2019-02-02 10:26**MOT test number** 629600472198**Result** ✓ Passed**MOT #9** 2018-02-27 13:53**MOT test number** 767799925793**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #8** 2018-02-27 10:36**MOT test number** 780478261793**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit 2mm (4.1.E.1)**MOT #7** 2017-02-24 17:09**MOT test number** 846572247902**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-02-23 11:24**MOT test number** 808612252527**Result** ✓ Passed**Advice** Engine covers and undertrays fitted obscuring some components**MOT #5** 2015-02-25 10:48**MOT test number** 205466955091**Result** ✓ Passed**Notice** Nail in nearside rear tyre**Notice** Items removed from driver's view prior to test**Notice** Under-trays fitted obscuring some underside components

**MOT #4** 2014-02-12 12:03**MOT test number** 418033844061**Result** ✓ Passed**MOT #3** 2014-02-11 16:00**MOT test number** 545122644063**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2012-09-28 10:26**MOT test number** 935082272275**Result** ✓ Passed**MOT #1** 2012-02-13 16:36**MOT test number** 758234542082**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>AK09BHW</b>
Plate since	2019-03-29
Current registration	<b>AK09BHW</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-03-06
Last registration	2022-02-26
Complete history	<a href="#">See info</a>



Registration #1	2009-03-06	6 mi
Registration #2	2012-02-13	25.200 mi
Registration #3	2012-09-28	29.799 mi
Registration #4	2014-02-11	38.112 mi
Registration #5	2014-02-12	38.121 mi
Registration #6	2015-02-25	47.369 mi
Registration #7	2016-02-23	57.586 mi
Registration #8	2017-02-24	67.589 mi
Registration #9	2018-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi
Registration #15	2019-05-29	75.277 mi
Registration #16	2019-05-29	75.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Number of axles**

2

**Engine number**

BXE B16696