



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-28
Pictures	6
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	43
Total items failed	6

## MOT #13 2023-09-13 11:25

MOT test number 214956761984

Result ✓ Passed

Next expiry date 2024-09-21

- Advice** Suspension arm corroded but not seriously weakened both rear lowers (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases cracking off (6.1.2 (a))
- Advice** Tyre worn close to legal limit/worn on edge both rears (5.2.3 (e))

## MOT #12 2022-09-14 12:21

MOT test number 572199768275

Result ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes (5.3.4 (a) (i))
- Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))
- Advice** Rear Exhaust has a minor leak of exhaust gases and centre rusty (6.1.2 (a))

**MOT #11**

2021-09-22 16:11

**MOT test number**

602279353014

**Result**

✓ Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**MOT #10**

2021-09-13 10:45

**MOT test number**

383957949425

**Result**

✗ Failed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Offside Headlamp aim too high (4.1.2 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #9**

2020-09-09 07:44

**MOT test number**

883459103847

**Result**

✓ Passed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #8**

2019-09-06 10:05

**MOT test number**

314803450402

**Result**

✓ Passed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2019-09-06 10:05

**MOT test number**

382481158538

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** Child Seat fitted not allowing full inspection of adult belt

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #6** 2018-08-29 08:56**MOT test number** 827289903611**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #5** 2017-09-12 08:45**MOT test number** 550648929871**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt All rear seats**MOT #4** 2016-08-31 12:36**MOT test number** 183246098076**Result** ✓ Passed**Advice** Near side front tyre worn very low on its inner edge**Advice** Rear exhaust has a minor leak**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2015-09-11 12:08**MOT test number** 696149917929**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' stone chip (8.3.1a)**Advice** Child seats fitted not allowing full inspection Of adult belts



MOT #2	2014-09-08 14:43
MOT test number	507091954206
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Passenger seat(s) missing at time of test

MOT #1	2013-09-05 12:12
MOT test number	348478743206
Result	✓ Passed
Notice	Child seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
21 September 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	215
<b>MOT expiry date</b>	21 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-13
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2010-09-13	24 mi
Registration #2	2013-09-05	25.143 mi
Registration #3	2014-09-08	33.726 mi
Registration #4	2015-09-11	42.457 mi
Registration #5	2016-08-31	51.765 mi
Registration #6	2017-09-12	61.371 mi
Registration #7	2018-08-29	69.356 mi
Registration #8	2019-09-06	81.500 mi
Registration #9	2020-09-06	93.644 mi
Registration #10	2021-09-06	105.788 mi
Registration #11	2022-09-06	117.932 mi
Registration #12	2023-09-13	130.076 mi
Registration #13		
Registration #14		
Registration #15		

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

AU21080