



report date: 2024-03-29

General information

Make	JAGUAR
Model	XK CONVERTIBLE
Colour	Blue
Year of manufacture	2007
Top speed	155 mph
0 - 60 mph	6.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption


Power	294 BHP
Max. torque	410 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.5 mpg
Consumption extra urban	34.9 mpg
Consumption combined	25.0 mpg
CO2 emission	269 g/km
CO2 label	M





Internet history

Entry 1	
Date	2021-07-16
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-18
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	33
Total items failed	7

MOT #17	2023-08-19 08:27
MOT test number	424879986784
Result	✓ Passed
Next expiry date	2024-08-18

MOT #16	2022-07-18 11:23
MOT test number	994242721675
Result	✓ Passed

MOT #15	2021-07-20 12:03
MOT test number	641512841901
Result	✓ Passed

MOT #14	2021-03-24 15:16
MOT test number	734845422571
Result	✓ Passed

**MOT #13** 2020-02-01 12:46**MOT test number** 266436337358**Result** ✓ Passed**Advice** Undertrays Conceal Underbody Components**Advice** General Underbody Component Corrosion**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #12** 2019-02-15 13:07**MOT test number** 247102324104**Result** ✓ Passed**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #11** 2019-02-12 16:23**MOT test number** 360895919433**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Inner Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2018-02-13 17:47**MOT test number** 163513953460**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Undertrays Conceal Underbody Components

**MOT #9** 2018-02-12 13:17**MOT test number** 958283661727**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Undertrays Conceal Underbody Components
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Fail** Offside Rear Mechanical brake component has restricted free movement (3.5.1k)

MOT #8 2017-02-24 14:06**MOT test number** 648773496835**Result** ✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Under trays fitted
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Engine covers fitted
- Advice** Exhaust system corroding slight leak from joints

MOT #7 2016-01-25 15:02**MOT test number** 845550064355**Result** ✓ Passed

- Advice** Both rear tyres wearing low

**MOT #6** 2015-02-25 09:59**MOT test number** 617416555075**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Under-trays fitted obscuring some underside components**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5** 2014-02-24 11:05**MOT test number** 646515254077**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Exhaust system corroding**Notice** Under-trays fitted obscuring some underside components**Notice** All brake discs slightly worn**MOT #4** 2014-02-24 11:05**MOT test number** 677845054060**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Exhaust system corroding**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Under-trays fitted obscuring some underside components**Notice** All brake discs slightly worn**Pass with rectification** Front registration plate letter/figure incomplete (6.3.1c)



MOT #3 2012-09-19 17:01

MOT test number 326703762295

Result ✓ Passed

MOT #2 2012-09-18 13:19

MOT test number 615742262272

Result ✗ Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #1 2011-03-05 12:48

MOT test number 718244661056

Result ✓ Passed

Notice Mark on n/s/r tyre



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
18 August 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	18 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	YJ57NUB
Plate since	2019-09-29
Current registration	YJ57NUB
Plate since	2019-09-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-12
Last registration	2023-08-19
Complete history	See info



Registration #1	2007-12-12	20 mi
Registration #2	2011-03-05	18.973 mi
Registration #3	2012-09-18	30.687 mi
Registration #4	2012-09-19	30.858 mi
Registration #5	2014-02-24	42.457 mi
Registration #6	2015-02-25	50.131 mi
Registration #7	2016-01-25	57.697 mi
Registration #8	2017-02-24	64.723 mi
Registration #9	2018-02-12	71.202 mi
Registration #10	2019-05-29	75.377 mi
Registration #11	2019-05-29	75.377 mi
Registration #12	2019-05-29	75.377 mi
Registration #13	2019-05-29	75.377 mi
Registration #14	2019-05-29	75.377 mi
Registration #15	2019-05-29	75.377 mi
Registration #16	2019-05-29	75.377 mi
Registration #17	2019-05-29	75.377 mi
Registration #18	2019-05-29	75.377 mi

More info >



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4791 mm
Wheel base	2752 mm
Kerb weight	1635 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	07032609435G