

Ford



General information

Make	FORD
Model	B-MAX ZETEC
Colour	Silver
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	77 kW / 105 HP / 104 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	44.1 mpg
CO2 emission	149 g/km
CO2 label	F







Internet history

Entry 1	
Date	2021-12-31
Pictures	38
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-28
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	15
Total items failed	3

MOT #12		2023-12-04 16:29
MOT test	number	169051206910
Result		✓ Passed
Next expiry date 2024-12-28		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #11	2023-12-04 10:27	
MOT test number	366155576480	
Result	🗙 Failed	
Fail Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))		
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weaken	ed (1.1.14 (a) (ii))	

MOT #10		2022-12-20 09:30
MOT test	number	735753911988
Result		✓ Passed
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1	.14 (a) (ii))





MOT #9		2021-12-29 08:49
MOT test	number	623667751638
Result		✓ Passed
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front head lamp beam image dim	
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a)	(i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

MOT #8	2020-11-18 12:14
MOT test number	178279862754
Result	✓ Passed

MOT #7	2019-11-20 16:12
MOT test number	886306729234
Result	✓ Passed

MOT #6		2019-11-20 16:12
MOT test number		424868430522
Result		🗙 Failed
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #5	2019-04-20 10:11
MOT test number	356428919236
Result	✓ Passed
Advice Oil leak, but not excessive slight leak oil (8.4.1 (a) (i))	

CarCheck.co.uk





MOT #4	2019-04-20 10:11
MOT test number	453212769474
Result	× Failed
Pass with rectification Nearside F	ront Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice Oil leak, but not excessive s	ight leak oil (8.4.1 (a) (i))
МОТ #3	2018-04-14 08:25
MOT test number	703326514946
Result	✓ Passed
MOT #2	2017-04-22 08:41
MOT test number	852916935446
Result	✓ Passed
MOT #1	2016-04-15 11:26
MOT test number	377026848250
Result	✓ Passed
Advice Offside Front Tyre worn clos	e to the legal limit (4.1.E.1)



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	✓ MOT Expires: 28 December 2024
Tax status	Valid until 1 January
Days left	247
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-28
Last registration	2023-12-04
Complete history	See info



Registration #1	2013-06-28	15 mi
Registration #2	2016-04-15	19.427 mi
Registration #3	2017-04-22	24.138 mi
Registration #4	2018-04-14	28.024 mi
Registration #5	2019-04-20	37.028 mi
Registration #6	2019-04-20	37.028 mi
Registration #7	2019-11-20	42.230 mi
Registration #8		10.200 est
Registration #9		11.777 esi
		11.227 est
Registration #9		01.000 est 01.000 est 01.000 est
Registration #9 Registration #10		00.000 est 0.000 est 00.000 est 00.000 est
Registration #9 Registration #10 Registration #11		00.000 est 0.000 est 00.000 est 00.000 est 00.000 est





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	92%
Children	84%
Pedestrian	67%
Safety systems	71%
Overall rating	83%
Video	see crash video



Dimensions & weight	
Width	2067 mm
Height	1604 mm
Length	4077 mm
Wheel base	2489 mm
Kerb weight	1208 kg
Max. allowed weight	1780 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12