



report date: 2024-03-28

General information

Make	FIAT
Model	GRAND PUNTO SOUND
Colour	White
Year of manufacture	-
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	<a href="#">View report</a>



source: autoonline.co.uk

**MOT history**

<b>MOT #13</b>	2022-01-06 17:34
<b>MOT test number</b>	468059346823
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-01-05
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))

<b>MOT #12</b>	2022-01-06 17:34
<b>MOT test number</b>	586445406406
<b>Result</b>	✗ Failed
<b>Pass with rectification</b>	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
<b>Advice</b>	Offside Front Coil spring corroded (5.3.1 (b) (i))

<b>MOT #11</b>	2020-11-02 15:37
<b>MOT test number</b>	736293604956
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge worn edge, and deep cracking in tread (5.2.3 (e))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
<b>Advice</b>	Coil spring corroded both rear (5.3.1 (b) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing deep cracking in tread (5.2.3 (d) (ii))
<b>Advice</b>	Offside Front Coil spring corroded very corroded (5.3.1 (b) (i))

**MOT #10** 2020-11-02 11:22**MOT test number** 655263812510**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Coil spring corroded both rear (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge worn edge, and deep cracking in tread (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Offside Front Coil spring corroded very corroded (5.3.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing deep cracking in tread (5.2.3 (d) (ii))**MOT #9** 2019-11-01 13:04**MOT test number** 473938386308**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear exhaust box poor**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-10-23 09:44**MOT test number** 609308558109**Result** ✓ Passed**MOT #7** 2017-11-06 14:28**MOT test number** 194441580963**Result** ✓ Passed

**MOT #6** 2016-09-21 16:42**MOT test number** 350429726473**Result** ✓ Passed**Advice** Nearside rear tyre deteriorated/cracking and tread approx' 3mm remaining**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-09-21 09:02**MOT test number** 313906916507**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside rear tyre deteriorated/cracking and tread approx' 3mm remaining**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-09-29 13:15**MOT test number** 213359734920**Result** ✓ Passed**Advice** Both front and nearside rear tyres deteriorated**MOT #3** 2015-09-29 09:19**MOT test number** 967095579025**Result** ✗ Failed**Advice** Both front and nearside rear tyres deteriorated**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-09-23 11:08**MOT test number** 886616864225**Result** ✓ Passed



MOT #1	2013-09-26 11:46
MOT test number	279059863283
Result	✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-27
Last registration	2022-01-06
Complete history	<a href="#">See info</a>



Registration #1	2010-09-27	13 mi
Registration #2	2013-09-26	11.570 mi
Registration #3	2014-09-23	16.862 mi
Registration #4	2015-09-29	23.072 mi
Registration #5	2015-09-29	23.072 mi
Registration #6	2016-09-21	27.801 mi
Registration #7	2016-09-21	27.801 mi
Registration #8	2017-11-06	33.502 mi
Registration #9	2018-05-22	35.277 mi
Registration #10	2018-05-22	35.277 mi
Registration #11	2018-05-22	35.277 mi
Registration #12	2018-05-22	35.277 mi
Registration #13	2018-05-22	35.277 mi
Registration #14	2018-05-22	35.277 mi
Registration #15	2018-05-22	35.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------