



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V EXTRA
Colour	White
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-03-11
Pictures	27
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-03-05
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	28
Total items failed	20

MOT #112023-03-06 17:39

MOT test number369142451463

Result✓ Passed

Next expiry date2024-03-05

Minor Windscreen damaged but not adversely affecting driver's view Cracked and various chipped areas (3.2 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))



MOT #10	2023-02-23 09:11
MOT test number	965923024358
Result	✗ Failed

Fail Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Rear Body component damaged and likely to cause injury Lamp casing sharp smashed (6.2.1 (a) (i))

Advice Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))

Fail Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))

Minor Hazard warning switch faulty (4.4.2 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Fail Nearside Rear Parking brake inoperative on one side Cable/caliper lever seized forward (1.4.1 (a))

Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Offside Rear Brake pipe excessively corroded Main before hose (1.1.11 (c))

Fail Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Fail Central Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Brake hydraulic reservoir close to minimum mark Topped up to eliminate light on dash (1.1.10 (d) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Minor Windscreen damaged but not adversely affecting driver's view Cracked and various chipped areas (3.2 (a) (i))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Brake pipe excessively corroded Main before hose (1.1.11 (c))

**MOT #9** 2022-02-21 16:35**MOT test number** 344638881496**Result** ✓ Passed**MOT #8** 2022-02-21 16:35**MOT test number** 289962113667**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2021-07-22 16:11**MOT test number** 714714044688**Result** ✓ Passed**Advice** Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #6** 2021-07-22 13:05**MOT test number** 527059652238**Result** ✗ Failed**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #5** 2020-05-21 09:08**MOT test number** 297883075137**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #4** 2020-05-21 09:08**MOT test number** 709012984231**Result** ✗ Failed**Pass with rectification** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #3** 2019-04-16 11:05**MOT test number** 924944348395**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #2** 2018-04-05 08:50**MOT test number** 444841783168**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2017-04-06 12:03**MOT test number** 230982745662**Result** ✓ Passed



Tax & MOT check

✓

Taxed

Tax due:
1 March 2025

✗

MOT

Expired:
5 March 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	5 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-30
Last registration	2023-03-06
Complete history	See info



Registration #1	2014-06-30	16 mi
Registration #2	2017-04-06	43.359 mi
Registration #3	2018-04-05	56.281 mi
Registration #4	2019-04-16	69.979 mi
Registration #5	2020-05-21	82.137 mi
Registration #6	2020-05-21	82.137 mi
Registration #7	2021-07-22	96.378 mi
Registration #8	2023-03-06	100.000 mi
Registration #9	2023-03-06	100.000 mi
Registration #10	2023-03-06	100.000 mi
Registration #11	2023-03-06	100.000 mi
Registration #12	2023-03-06	100.000 mi
Registration #13	2023-03-06	100.000 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1971 mm
Length	5399 mm
Kerb weight	1710 kg
Max. allowed weight	2790 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	C155405